

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

X Initial Report ~~Final Report~~

Name of Company CHEVRON	Contact Larry Williams	
Address P.O. Box 1949 Eunice NM. 88231	Telephone No. 505-394-1247 (office), 505-390-7165 (cell)	
Facility Name- Leonard C Battery	Facility Type - Production Battery	
Surface Owner- State	Mineral Owner - State of New Mexico	Lease No.


LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
	36	21S	36E					Lea

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release- Produced Water	Volume of Release 8 BW	Volume Recovered- 0 BBI
Source of Release- 1000 BBL Steel Tank	Date and Hour of Occurrence- 10/28/2007 12:25 pm	Date and Hour of Discovery 10/28/2007 12:25 pm.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Pat Caperton	
By Whom? Larry Williams	Date and Hour 10/29/2007 4:10 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	



If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
Water transfer line going from heater to Rice's box got a hole in valve. The water soaked up inside our secondary containment inside our battery. No Remediation will be done at this time.

Describe Area Affected and Cleanup Action Taken.* All fluid was contained within our secondary containment of our battery.
Chlorides 32,000 ppm Ground water 125'

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Larry Williams</i>	OIL CONSERVATION DIVISION	
Printed Name: Larry Williams	<i>J. Johnson</i> Approved by District Supervisor ENVIRONMENTAL ENGINEER	
Title: Operations Rep	Approval Date: 12.14.07	Expiration Date: 2.14.08
E-mail Address: LCWL@chevron.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 11/26/2007 Phone: 505-394-1247	*VERTICAL DELINEATION	

* Attach Additional Sheets If Necessary

REQUIRED.

RP# 1689