

District I
1625 N French Dr, Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

X Initial Report **X Final Report**

Name of Company CHEVRON	Contact Larry Williams	
Address P.O. Box 1949 Eunice NM. 88231	Telephone No. 505-394-1247 (office), 505-390-7165 (cell)	
Facility Name- C H Weir B Battery	Facility Type - Production Battery	
Surface Owner- S & W Cattle Co./ Trent Stradley	Mineral Owner - Mary B Weir	Lease No.

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
O	12	20S	37E					Lea

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release- Produced Water	Volume of Release 20 BW	Volume Recovered- 6 BBI
Source of Release- 3' poly & PVC pipe connection	Date and Hour of Occurrence- 11/30/2007 10:25 am	Date and Hour of Discovery 11/30/2007 10:25 am.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Pat Caperton	
By Whom? Larry Williams	Date and Hour 12/3/2007 11:10 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	


If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
Water transfer line going from battery to Skaggs disposal got small leak in connection between poly and PVC pipe. Picked up standing water and disposed of it at a third party disposal. Dug out leak and made repairs.

Describe Area Affected and Cleanup Action Taken.* 15' x 20' area off the West side pad of MB Weir B 13. We will dig up and haul off known contaminated soil and test for chlorides. Then proceed with cleanup as needed.

Chlorides 32,000 ppm Ground water 70'

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Larry Williams	 Approved by District Supervisor ENVIRONMENTAL ENGINEER	
Title: Production Rep	Approval Date: 12.18.07	Expiration Date: -
E-mail Address: LCWL@chevron.com	Conditions of Approval:	
Date: 12/03/2007 Phone: 505-394-1247	Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary

RP# 1688