


- LEGEND
- ▲ RECOVERY WELL LOCATION
 - MONITORING WELL LOCATION
 - Ⓐ MONITORING WELL LOCATION (DEEP)
 - ⊙ WATER WELL LOCATION (INACTIVE)
 - 207 CHLORIDE CONCENTRATION (mg/L)
 - CHLORIDE ISOCONCENTRATION CONTOUR (mg/L)
 - NA = NOT ANALYZED

GW - 003

2006 MONITORING REPORTS

DATE:
03/12/2007



SIGNATURE	DATE
REVIEW ENGINEER:	
PROJECT ENGINEER:	
PROJECT MANAGER:	
CLIENT:	
PREPARED BY:	
 SECOR 2321 CLUB MERIDIAN DRIVE, SUITE E OKEMOS, MICHIGAN	
PREPARED FOR:	
CHEVRON EUNICE SOUTH GAS PLANT EUNICE, NEW MEXICO	
FOURTH QUARTER 2006 SHALLOW WELL CHLORIDE ISOCONCENTRATION MAP	
DESIGNED BY: BAL	CHECKED BY: MP
DATE: 12/20/06	CAD FILE: Eunice South Basemap 2006
PROJECT No: 89CH.49389.72	DRAWING SCALE: AS SHOWN

Figure 15