

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

### Release Notification and Corrective Action

#### OPERATOR

☒ Initial Report

☐ Final Report

Name of Company <u>Fasken Oil and Ranch, Ltd.</u>	Contact <u>Jimmy D. Carlile</u>
Address <u>303 W. Wall, Ste 1800 Midland, TX 79701</u>	Telephone No. <u>432 687-1777</u>
Facility Name <u>Denton SWD</u>	Facility Type <u>Salt Water Disposal Station</u>

Surface Owner <u>Darr Angell</u>	Mineral Owner <u>Fee</u>	Lease No. <u></u>
----------------------------------	--------------------------	-------------------

#### LOCATION OF RELEASE API# 3002505309 0000

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
<u>D</u>	<u>13</u>	<u>15S</u>	<u>37E</u>					<u>Lea</u>

Latitude ~50' Longitude

#### NATURE OF RELEASE

Type of Release <u>Produced Water</u>	Volume of Release <u>950</u>	Volume Recovered <u>910</u>
Source of Release <u>6" injection line</u>	Date and Hour of Occurrence	Date and Hour of Discovery
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? <u>1/5/08 5pm</u>	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

NA

Describe Cause of Problem and Remedial Action Taken.\*

6" injection line separated, injection pump immediately shut down. Line is being repaired.

Describe Area Affected and Cleanup Action Taken.\*

Affected area inside the dike on the southern end of the facility. No fluids left the diked area. Fluids were picked up by vacuum truck and hauled to a disposal. No additional remediation planned at this time as this is an active SWD site.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <u>Jimmy D. Carlile</u>	OIL CONSERVATION DIVISION <u>Johnson</u>	
Printed Name: <u>Jimmy D. Carlile</u>	Approved by District <u>ENVIRONMENTAL ENGINEER</u>	
Title: <u>Regulatory Affairs</u>	Approval Date: <u>1.8.08</u>	Expiration Date: <u>3.10.08</u>
E-mail Address: <u>jimmynyc@for1.com</u>	Conditions of Approval: <u>VERTICAL DECONTAMINATION</u>	Attached <input type="checkbox"/>
Date: <u>1/7/08</u>	Phone: <u>432 687-1777</u>	

\* Attach Additional Sheets if Necessary

WILL BE REQUIRED BY

RPH# 1706