

3R - 0386

**GENERAL
CORRESPONDENCE**

2007



Lodestar Services, Inc.

P.O. Box 3861, Farmington, NM 87499-3861, 505-334-2791

3R0386

RECEIVED

2007 NOV 7 PM 2 26

October 30, 2007

Mr. Bill Freeman
Navajo Nation Environmental Protection Agency
Old DNR Building (Bldg # 008-090)
Window Rock Blvd
PO Box 339
Window Rock, AZ 86515

CERTIFIED MAIL: 7006 2150 0001 7643 8493

RE: OH Randel #7

Dear Mr. Freeman,

This letter serves to alert the Navajo Nation EPA of work to be conducted at the OH Randel #7. The well site is located in Unit D of Section 16 of Township 26N, Range 11W, and includes six groundwater monitoring wells installed to investigate groundwater quality. XTO Energy, Incorporated (XTO) has hired Lodestar Services, Incorporated (Lodestar) to oversee groundwater monitoring at the site. A site map is attached for your review.

Lodestar visited the site in August 2007 to collect quarterly groundwater samples and discovered that groundwater monitoring well MW-5 had been damaged beyond repair. XTO intends to replace MW-5 on November 12, 2007 so that it can continue to be sampled on a quarterly basis to monitor progress at the site.

Should you have any questions or require additional information, please do not hesitate to contact Lisa Winn at 505-333-3196 or you may call me at 970-946-1093.

Sincerely,

LODESTAR SERVICES, INC

Ashley L. Ager

Cc: Martin Nee, Lodestar Services
Lisa Winn, XTO Energy
Kim Champlin, XTO Energy
Jim Walker, USEPA Region 9
Brandon Powell, NMOCD
Glen Von Gonten, NMOCD
File

Attachments: Site Map



Lodestar Services, Inc.

P.O. Box 3861, Farmington, NM 87499-3861, 505-334-2791

