

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Apache Oil Corporation	Contact	Natalie Gladden
Address	P.O. Box 1849	Telephone No.	505-390-4186
Facility Name	Owen B Battery Well #10	Facility Type	Battery

Surface Owner	Bill Stephens	Mineral Owner		API #	30-025-35638
---------------	---------------	---------------	--	-------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
M	34	21S	37E	1137'	South Line	485'	West Line	Lea

Latitude N deg 25.904 Longitude W 103 deg 09.419

NATURE OF RELEASE

WTR 75'

Type of Release	Oil/Water	Volume of Release	5-25bbls	Volume Recovered	0 bbls
Source of Release	Oil Hauler		3/21/08		03/22/08
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?		Date and Hour			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

RESIDENT
DINK TEATHER CLAIM NO
WTR IN IMMEDIATE AREA
DELU W/O SUCCESS.

Describe Cause of Problem and Remedial Action Taken.*



Taylor Transport was loading truck and fell asleep.

Describe Area Affected and Cleanup Action Taken.*

Area is 200' x approx 17' wide. It is estimated that more than 5 bbls and less than 25 bbls was released. Clean up is being performed currently. All visible hydrocarbons are being hauled to Sundance. Hydrocarbons and chlorides will be tested and cleaned to State Standards.

3400' - REPORTED QUANTITY NOT AGREE W/OCD FIGURES.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Natalie Gladden	Approved by District  ENVIRONMENTAL ENGINEER	
Title: EH&S Environmental Technician	Approval Date: 4-3-08	Expiration Date: 6-6-08
E-mail Address: natalie.gladden@apachecorp.com	Conditions of Approval:	
Date: 4/2/08 Phone: 505-390-4186	Submitted Final C-141 w/ DOCUMENTATION	
		Attached <input type="checkbox"/> 1 RP. 1832

* Attach Additional Sheets If Necessary

f C/HO 809 432 986