

District I
1625 N French Dr, Hobbs, NM 88240
District II
1301 W Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S St Francis Dr, Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised October 10, 2003

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company DCP Midstream, LP	Contact Johnnie Bradford	
Address 10 Desta Drive, Suite 400 W, Midland, TX 79705	Telephone No. & E-mail 432 .620.4166 jbradford@dcpmidstream.com	
Facility Name Eddy County Loop Line	Facility Type Pipeline (Eddy County Loop Line)	
Surface Owner	Mineral Owner	Lease No.

LOCATION OF RELEASE

Unit Letter	Section 35	Township 18	Range 35	Feet from the 300	North/South Line N	Feet from the 1400	East/West Line W	County LEA
-------------	---------------	----------------	-------------	----------------------	-----------------------	-----------------------	---------------------	---------------

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release Liquids and Sour Gas	Volume of Release Unknown	Volume Recovered Un-estimated
Source of Release Hole in Pipeline	Date and Hour of Occurrence	Date and Hour of Discovery 02/27/2008 12:30
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? OCD Chris Williams by telephone	
By Whom? Johnnie Bradford	Date and Hour 02/28/2007 10 00	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

n/a

Describe Cause of Problem and Remedial Action Taken *

A third party working in the area of a DCPM pipeline notified a DCPM Field Operator of a leak on the Eddy County Loop line (COP line #12200). The leak had been ongoing for sometime prior to discovery; therefore, the extent of the contamination is unknown.

Describe Area Affected and Cleanup Action Taken *

The area affected was the pipeline right of way just east of hwy 238 approx. 0.5 miles. Depth to groundwater is presumed to be 50 ft. bgs. All effected soils will be tested for TPH and BTEX (process knowledge constituents of DCPM pipeline), remediated, and hauled to an NMOCD approved disposal site. After all contaminated soil is removed; this location will be backfilled with soil approved by the NMOCD.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Johnnie Bradford</i>	<u>OIL CONSERVATION DIVISION</u>	
Printed Name: Johnnie Bradford	Approved by District Supervisor: <i>Chris Williams</i>	
Title: SR. Environmental Spec.	Approval Date: 3/12/08	Expiration Date: 5/12/08
E-mail Address: jbradford@dcpmidstream.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 03/10/08	Phone: 432-620-4166	1RP-1839

* Attach Additional Sheets If Necessary

FCO# 81033781