

District I  
1625 N French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

## Release Notification and Corrective Action

### OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Apache Corporation	Contact	Natalie Gladden
Address	P.O. Box 1849 Eunice NM 88231	Telephone No.	505-390-4186
Facility Name	Southland Royalty A #8	Facility Type	Production

Surface Owner	Gary Deck	Mineral Owner		Lease No.	30-025-20069
---------------	-----------	---------------	--	-----------	--------------

### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
O	4	21S	37E	660	South Line	1990	East Line	Lea

Latitude N 32 deg 30.143' Longitude W 103 deg 09.951'

### NATURE OF RELEASE

Type of Release	Produced water	Volume of Release	>5 <10 bbls	Volume Recovered	0
Source of Release	Unknown	Occurrence:	5/8/08	Discovery:	5/8/08 10:10
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Larry Johnson		
By Whom?	Natalie Gladden		5/8/08 12:30		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*

RECEIVED

MAY 12 2008

Describe Cause of Problem and Remedial Action Taken.\* ☐ Hot oiler had hot watered well on 5/7/08 and when he finished loading well his truck went on vacuum and fluid was coming from around the wellhead, below ground surface. Dug out wellhead and no leaking occurred on 5/8/08. 5/9/08 backfilling around WH took place due to investigation. Heard large void and vibration when hotoil hot watered well. Unknown cause of leak. Area cleaned.

Describe Area Affected and Cleanup Action Taken.\*

Water had already soaked in. Once determination is figured out of cause of leak, location will be remediated to meet State Standards.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Natalie Gladden</i>	OIL CONSERVATION DIVISION	
Printed Name: Natalie Gladden	Approved by District <i>Larry Johnson</i> ENVIRONMENTAL ENGINEER	
Title: EH&S Environmental Tech	Approval Date: 5.14.08	Expiration Date: 7.14.08
E-mail Address: <a href="mailto:natalie.gladden@apachecorp.com">natalie.gladden@apachecorp.com</a>	Conditions of Approval:	
Date: 5/12/08 Phone: 505-390-4186	Submit from C.141 84	Attached <input type="checkbox"/> 1 RP # 1861

\* Attach Additional Sheets If Necessary

FWHO 813538952