

District I  
1625 N French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Form C-141  
Revised October 10, 2003

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

**OPERATOR**

Initial Report  Final Report

Name of Company: Targa Midstream Services L P	Contact: James Lingnau 505.394.2534, Chuck Tolsma 505.631.6026
Address: PO Box 1909 Eunice, NM 88231	Telephone No. (505) 394-2534
Facility Name: Eunice Gathering System	Facility Type
Surface Owner: Deck Estate Bowles	Mineral Owner:
Lease No. 30,025,374,00-00	

**LOCATION OF RELEASE**



Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
G	16	22S	37E					Lea

Latitude 32.23.198N Longitude 103.10.339W

**NATURE OF RELEASE**

Type of Release: Gas and Produced Liquids	Volume of Release: Unknown	Volume Recovered: None
Source of Release: 6" Pipeline Failure	Date and Hour of Occurrence: Unknown	Date and Hour of Discovery: Unknown
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken. * A Six inch gathering line had a leak and released gas and any produced liquids that were lying in the line. Line was repaired and possibly contaminated soil used for backfill. The line has since been taken out of service.		
Describe Area Affected and Cleanup Action Taken.* Targa will excavate and sample the area of contamination and remove any contaminated soil. The pipeline is out of service and capped. The old pipe in the contaminated area will be removed. The area will be cleaned and tested per OCD Guidelines.		

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Don Embrey		
Title: Advisor	Approved by District Supervisor:	<b>ENVIRONMENTAL ENGINEER</b>
E-mail Address: dembrey@targaresources.com	Approval Date: <u>7.8.08</u>	Expiration Date: <u>9.8.08</u>
Date: 4/01/08 Phone: (432) 688-0546	Conditions of Approval:	Attached <input type="checkbox"/>
	<b>SUBMIT FINAL C. 141</b>	<b>1 RPT# 1894</b>

\* Attach Additional Sheets If Necessary

**W/ SUPPORTING DOCUMENTATION**  
**BY 9.8.08**