

District I
1625 N. French
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr. Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☒ Final Report

Name of Company CHEVRON USA INC.	Contact Larry Williams
Address P.O. Box 1949 Eunice NM. 88231	Telephone No. 505-394-1247 (office), 505-390-7165 (cell)
Facility Name- B F Harrison B1	Facility Type - Battery

Surface Owner- JEAN SALSMAN	Mineral Owner - State of New Mexico	Lease No.
-----------------------------	-------------------------------------	-----------

LOCATION OF RELEASE

API 30.025.30200

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
C	9	23 S	37 E					Lea

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release- Produced Water	Volume of Release 7 BW	Volume Recovered- 3 BW
Source of Release- Nipple on transfer pump had crack in threads	Date and Hour of Occurrence- 11/02/2008 8:30 am	Date and Hour of Discovery 11/02/2008 8:00 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Larry Johnson	
By Whom? Donnie Ives	Date and Hour 11/03/2008 3:00 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken
Nipple in piping on water transfer pump got a crack in the threads of the nipple. Water was spraying out of threads. Picked up standing water.

Describe Area Affected and Cleanup Action Taken.*
Fluid was contained within secondary containment in an area 5' X 40'. Also had an area outside of secondary containment that is in the road of 8' x 26'. No further action will be done on clean up of battery.

DEPTH TO GW=90 ft.

Chlorides 28385

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Larry Williams	Approved by District Supervisor  ENVIRONMENTAL ENGINEER	
Title: Production Team Leader	Approval Date: 12.12.08	Expiration Date: _____
E-mail Address: lcwl@chevron.com	Conditions of Approval:	
Date: 11/03/2008 Phone: 505-394-1247	SUBMIT FINAL C.141	Attached <input type="checkbox"/> IRP# 2024

* Attach Additional Sheets If Necessary

WHEN CONTAMINATED SOIL
IS REMOVED - SUBMIT BILLS OF
LADEN FROM DISPOSAL.

FGR 0835251914