

District I
1625 N French Dr, Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr, Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



JUL 24 2008

OCD-ARTESIA

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

13EBC008A0294		OPERATOR		<input type="checkbox"/> Initial Report	<input type="checkbox"/> Final Report
Name of Company OXY USA		Contact Kelton Beaird			
Address 102 S Main Carlsbad, NM 88220		Telephone No. (O) 505-887-8337 C) 575-390-1903			
Facility Name Nagooltee Peak 5-1		Facility Type well			
NAGOOOTEE PEAK 5 FEDERAL COI					
Surface Owner BLM		Mineral Owner		Lease No.	

30 015 24713								
LOCATION OF RELEASE								
Unit Letter J	Section 5	Township 22S	Range 24E	Feet from the	North/South Line	Feet from the	East/West Line	County EDDY

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release Oil & Produced Water	Volume of Release 6bbls of oil 72 bbls of water	Volume Recovered 2bbls of oil 35 bbls of water
Source of Release ESD Vessel	Date and Hour of Occurrence Unknown	Date and Hour of Discovery 7-18-08 @ 8:30am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher NMOCD, Jim Amos BLM	
By Whom?	Date and Hour See above	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

The ESD Vessel did not shut causing the pop off valve to overflow. A vac-truck was called and all standing fluids were vacuumed up and disposed of.

Describe Area Affected and Cleanup Action Taken.*

The area affected was across the location into the pasture. The produced water is approx 1500ppm in Chlorides. The affected areas were washed with 40bbls. of fresh water and microblaze was put on to assist in the clean-up. This area will be monitored for further growth.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:		OIL CONSERVATION DIVISION	
Printed Name: Kelton Beaird		Approved by District Supervisor: T Cumby	
Title: HES Specialist		Approval Date: 06-08-09	Expiration Date: Aug 2, 2009
E-mail Address: kelton_beaird@oxy.com		Conditions of Approval:	
Date: 7-22-08		Attached <input type="checkbox"/> 2 RP-293	

* Attach Additional Sheets If Necessary