

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

JAN 08 2009

HOBBSOCD

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

X Initial Report ☐ Final Report



Name of Company	Oxy USA WTP	Contact	Dusty Wilson
Address	1017 W. Stanolind Rd	Telephone No.	(575) 397-8247
Facility Name	MLMU #78	Facility Type	Oil Well Site
Surface Owner	Jimmy Doom	Mineral Owner	Oxy
		Lease No.	30-025-10916

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
H	32	23s	37e		SE1/4 NE1/4			Lea

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release	Crude Oil and Produce Water	Volume of Release	4 bo 2 bw	Volume Recovered	0 bo 0 bw
Source of Release	3" poly line froze and ruptured.	Date and Hour of Occurrence	1/1/2009	Date and Hour of Discovery	1/1/2009 10:00 am
Was Immediate Notice Given?	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?	Date and Hour				
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. n/a			
If a Watercourse was Impacted, Describe Fully.* N/A WATER @ 70					
Describe Cause of Problem and Remedial Action Taken.* 3" poly line ruptured due to freezing temperatures. Site will be remediated to NMOCD guidelines.					
Describe Area Affected and Cleanup Action Taken.* Remediate to NMOCD Requirements.					
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.					
Signature: 		OIL CONSERVATION DIVISION			
Printed Name: Dusty L. Wilson		Approved by District Supervisor: 			
Title: HES Specialist		Approval Date: 01/12/09		Expiration Date: 03/13/09	
E-mail Address: dusty_wilson@oxy.com		Conditions of Approval: DELINEATE/REMEDIATE TO CLEAN+1		Attached <input type="checkbox"/>	
Date: _____ Phone: (575) 397-8210		SUBMIT FINAL C-141 BY 03/13/09		IRP-2045	

- Attach Additional Sheets If Necessary

FGRL 0901230348

New Mexico Office of the State Engineer
POD Reports and Downloads

Township: 23S Range: 37E Sections: 32

NAD27 X: Y: Zone: ☐ Search Radius:

County: ☐ Basin: ☐ Number: Suffix:

Owner Name: (First) (Last) ☐ Non-Domestic ☐ Domestic ☒ All

POD / Surface Data Report

Avg Depth to Water Report

Water Column Report

Clear Form

iWATERS Menu

Help

AVERAGE DEPTH OF WATER REPORT 01/08/2009

Bsn	Tws	Rng	Sec	Zone	X	Y	Wells	(Depth Water in Feet)		
								Min	Max	Avg
CP	23S	37E	32				1	106	106	106

Record Count: 1