

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised October 10, 2003

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company - Texas ReExploration Operating LC	Contact - Dean Brooks
Address - 3025 Maxroy, Houston, TX 77008	Telephone No. 713-622-2425
Facility Name - Western Reserve 34 Federal #1 (Tank Battery)	Facility Type - Tank Battery
Surface Owner - The Boothers	Mineral Owner - BLM
API No. 30-005-20708	

LOCATION OF RELEASE

Unit Letter B	Section 34	Township 07S	Range 31E	Feet from the South Line	Feet from the East/West Line	County Chaves
------------------	---------------	-----------------	--------------	-----------------------------	---------------------------------	------------------

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release - Produced Water/Saltwater -	Volume of Release - estimated 10bbbls	Volume Recovered - 0bbbls
Source of Release - Flow Line	Date and Hour of Occurrence. ?	Date and Hour of Discovery 4/2/08
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour -	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* The spill at this site is considered to be approximately 5 - 10bbbls. The cause of the leak was a flowline failure which was quickly repaired. No remedial action taken yet. The remediation plan is to remove contaminated soil and dispose of at nearest NMOCD approved disposal site. This plan will be implemented upon NMOCD approval. Please see attached photos.		
Describe Area Affected and Cleanup Action Taken.* The approximate area effected is 10yds ft X 30yds. The spill ran across the lease road area and along side the storage tanks. Any soil with elevated levels of chlorides will be removed. The choice of abatement is to remove contaminated soil and dispose of at the nearest NMOCD approved disposal site. in Chaves County.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		

Signature: <i>Dean Brooks</i>	OIL CONSERVATION DIVISION <i>Johnson</i>	
Printed Name: Dean Brooks	Approved by District Supervisor ENVIRONMENTAL ENGINEER	
Title: Vice President of Engineering	Approval Date: 1.22.09	Expiration Date: 3.22.09
E-mail Address: dbrooks@tex-rex.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 5/28/08	Phone: 713-622-2425	IRP# 09.1.2055

* Attach Additional Sheets If Necessary

PGRL0905640952