

District I  
1625 N French Dr, Hobbs, NM 88240  
District II  
1301 W Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S St Francis Dr, Santa Fe, NM 87505

**RECEIVED** State of New Mexico  
Energy Minerals and Natural Resources  
FEB 18 2009  
**HOBBSOCD** Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

**OPERATOR**  Initial Report  Final Report

Name of Company CHEVRON USA INC.	Contact Larry Williams
Address P.O. Box 1949 Eunice NM. 88231	Telephone No. 505-394-1247 (office), 505-390-7165 (cell)
Facility Name- B F Harrison B1	Facility Type - Battery

Surface Owner- JEAN SALSMAN	Mineral Owner - State of New Mexico	Lease No.
-----------------------------	-------------------------------------	-----------

**RP # 09-2-2082**

**LOCATION OF RELEASE**

**API # 30-025-30200**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
C	9	23 S	37 E					Lea

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

**NATURE OF RELEASE**

Type of Release- Produced Water and oil	Volume of Release 1 BO & 16 BW	Volume Recovered- 8 bbl of fluid
Source of Release- FWKO PSV	Date and Hour of Occurrence- 02/12/2009 8:00 am	Date and Hour of Discovery 02/12/2009 8:00 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Larry Johnson	
By Whom? Larry Williams	Date and Hour 02/12/2009 3:00 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*


Describe Cause of Problem and Remedial Action Taken  
Dump valve controller on FWKO stuck in the closed position causing vessel to dome out sending fluid to final gas scrubber. Gas scrubber couldn't keep up causing PSV to relieve on FWKO sending 16 BW and 1/2 BO into secondary containment Picked up standing fluid

Describe Area Affected and Cleanup Action Taken.\*  
Fluid was contained within secondary containment in an area 10' X 54'. Will remove stained soil and dress up battery. No further action will be done on clean up of battery.

DEPTH TO GW=85 to 90 ft.

Chlorides 28385 36.8 gravity oil

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>	
Printed Name. Larry Williams	Approved by District Supervisor. 	
Title: Production Team Leader	Approval Date: 02/27/09	Expiration Date: _____
E-mail Address. lcwl@chevron.com	Conditions of Approval:	
Date: 02/16/2009 Phone: 505-394-1247	Attached <input type="checkbox"/>	

\* Attach Additional Sheets If Necessary

FGRL 0905837095