

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505

RECEIVED

MAY 01 2009

HOBBS

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	Tempo Energy	Contact	Frank Pannell
Address	PO Box 1034 Midland, TX 79702	Telephone No.	(432)689-2951
Facility Name	State NNG #1	Facility Type	Oil Well

Surface Owner	STATE	Mineral Owner		Lease No.	30-025-28245
---------------	-------	---------------	--	-----------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
L	16	26	32E					Lea

Latitude _____ Longitude _____

NATURE OF RELEASE



Type of Release	Produced water	Volume of Release	10 bbl	Volume Recovered	
Source of Release	Overflow of water tank	Date and Hour of Occurrence		Date and Hour of Discovery	
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?		Date and Hour			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*	WATER @ 2.15'
---	---------------

Describe Cause of Problem and Remedial Action Taken.*	SWD flow line clogged, causing water tank to overflow into dyke around tank SWD Flow line was hot watered and flushed out.
---	--

Describe Area Affected and Cleanup Action Taken.*	Area affected was dyke around water and oil tanks. Roadrunner Environmental was called in and vacuumed up fluids, then dug out contaminated soil using back-hoe and hauled to Controlled Recovery, Inc. Covered area with clean caliche and rebuilt containment walls around battery Also dug out and remediated area around wellhead where small leak from packing had occurred over time.
---	---

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Frank Pannell	Approved by: ENV ENGINEER District Supervisor: 	
Title: VP Operations	Approval Date: 05/08/09	Expiration Date: _____
E-mail Address: tempoenergy@suddenlink.net	Conditions of Approval: _____	Attached <input type="checkbox"/>
Date: 4/30/09	Phone: (432)689-2951	IRP-09-4-2157

* Attach Additional Sheets If Necessary