

District I  
1625 N French Dr., Hobbs, NM 88240  
District II  
1301 W Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S St Francis Dr., Santa Fe, NM 87505

RECEIVED

JUN 05 2009

HOBBSD

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Americo Energy Resources, LLC	Contact	Oscar Nosrati
Address	7575 San Felipe STE 200 Houston, TX 77063	Telephone No.	713 984-9700
Facility Name	State T battery	Facility Type	Production
Surface Owner	PRIVATE	Mineral Owner	
		Lease No.	B-9774

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
K	2	15S	37E					LEA

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_ NEARBY WELL STATE T 005  
API # 30.025.05230.00.00

NATURE OF RELEASE

Type of Release	Salt Water	Volume of Release	35bbls	Volume Recovered	34bbls
Source of Release		Date and Hour of Occurrence	5/17/09 8am	Date and Hour of Discovery	5/17/09 8am
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mossy Brown		
By Whom?	Bruce Madden	Date and Hour			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*



Production heater treater had a hole in bottom. The wells were immediately shut down. Vacuum trucks were called to location. 35bbls of produced water with trace of skim oil was released. 34 bbls were recovered.

WATER @ 45'

Describe Area Affected and Cleanup Action Taken.\*

No fluids escaped outside of firewall. Repairs are being made to the heater treater.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION		
Printed Name: Ehsan Bayat	Approved by <del>District Supervisor</del> ENV ENGR 		
Title: Regulatory Analyst/Production Technician	Approval Date: 06-08-09	Expiration Date: 08-07-09	
E-mail Address: Ehsan.bayat@americoenergy.com	Conditions of Approval: DELINEATE & REMEDIATE TO CLEAN UP INSIDE THE CONTAINMENT AREA SUBMIT		Attached <input type="checkbox"/>
Date: 5/21/09	Phone: 713-984-9700	IRP.09.6.2195	

\* Attach Additional Sheets If Necessary

FINAL C-141 BY 08/07/09

FGR L0915957572