

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

RECEIVED
State of New Mexico
Energy Minerals and Natural Resources
JUN 08 2009
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company ConocoPhillips Company	Contact Ron Robinson
Address 3300 North A St. Bldg 6, Midland Tx. 79705-5406	Telephone No. 575-390-4923
Facility Name EVGSAU 3456-006	Facility Type: CO2 Injection well

Surface Owner: State Of New Mexico	Mineral Owner: State Of New Mexico	Lease No. 30-025-2639000
------------------------------------	------------------------------------	--------------------------

LOCATION OF RELEASE

Unit Letter D	Section 34	Township 17-S	Range 35E	Feet from the 166'	North/South Line FNL	Feet from the 1155'	East/West Line FWL	County LEA
------------------	---------------	------------------	--------------	-----------------------	-------------------------	------------------------	-----------------------	---------------

Longitude
Latitude -103.450311921207

Latitude
Longitude 32.7981601052959

NATURE OF RELEASE

Type of Release: Well control fluids 10# brine/water base mud	Volume of Release: 41.53 bbls	Volume Recovered: 16 bbls
Source of Release: 5.5 production casing failure	Date and Hour of Occurrence: 5/27/2009 Unknown	Date and Hour of Discovery: 5/28/2009 @ 0630hr MST
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

WATER @ 63'



Describe Cause of Problem and Remedial Action Taken.*

Well work being done, 5/27/2009 well was shut in over night with 14# mud on back side 5.5 casing failure resulted in surface casing 135/8 over pressure and it too failed. Resulting in release to ground of brine and water based mud.

Describe Area Affected and Cleanup Action Taken.*

Affected area consisted of 130'x265'x.75" calculated volume of 23.53bbls. On Monday 6-01-2009 an additional 17bbls was picked up from location resulting in release volume of 41bbls. Spill site will be delineated and remediated in accordance with NMOCD guidelines.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Ron Robinson		ENV ENGR Approved by District Supervisor: 	
Title: Projects HSE Lead		Approval Date: 06/08/09	Expiration Date: 08/07/09
E-mail Address: ron.e.robinson@conocophillips.com		Conditions of Approval: SUBMIT FINAL C-141 BY 08/07/09.	
Date: 6-5-2009	Phone: 575-390-4923	Attached <input type="checkbox"/> IRP-09-6-2199	

* Attach Additional Sheets If Necessary

FGRL0916232021