

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED
JUN 15 2009
HOBBSD

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	COG OPERATING LLC	Contact	Chasity Jackson
Address	550 W. Texas, Suite 1300 Midland, TX 79701	Telephone No.	432-686-3087
Facility Name	Pronghorn SWD Pipeline	Facility Type	Water Pipeline
Surface Owner	Federal	Mineral Owner	
		Lease No.	30-025-32735

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
J	3	18S	32E					

Latitude N 32 degrees 46.450 Longitude W 103 degrees 44.997

NATURE OF RELEASE

Type of Release-Produced Water	Volume of Release-30bbls	Volume Recovered- 10bbls
Source of Release- 8" PVC Dresser Sleeve	Date and Hour of Occurrence- 6/7/09- 12:00 pm	Date and Hour of Discovery 6/7/09-12:00pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Larry Johnson, NMOCD Lea Co. District I Trish Badbear, BLM Field Inspector, Lea Co.	
By Whom? Pat Ellis	Date and Hour 6/9/09 @ 1:00pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

WATER @ 20'

Describe Cause of Problem and Remedial Action Taken.*

Dresser sleeve gasket seal failure. Replace Complete Dresser sleeve assembly

Describe Area Affected and Cleanup Action Taken.*

Approx. 15' X 150' of ROW was affected by produced water. Recovered 10bbls. The surface saturation was at a depth of 2". All contaminated soil on ROW has been excavated and removed.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Chasity Jackson</i>	OIL CONSERVATION DIVISION	
Printed Name: Chasity Jackson	Approved by ENV ENGR: <i>Stephany LeKing</i> District Supervisor:	
Title: Agent for COG	Approval Date: 06/15/09	Expiration Date: 08/14/09
E-mail Address: cjackson@conchoresources.com	Conditions of Approval: DELINEATE AND REMEDIATE TO CLEAN + 1 PER NMOCD GUIDELINES. SUBMIT	Attached <input type="checkbox"/>
Date: 06/10/09 Phone: 432-686-3087	IRP-09-6-2209 FINAL C-141 BY 08/14/09.	

* Attach Additional Sheets If Necessary

FGRL0916653423