

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company Yates Petroleum Corporation	OGRID Number 25575	Contact Robert Asher
Address 104 S. 4 TH Street	Telephone No. 505-748-1471	
Facility Name Livingston Ridge Water System	API Number 30-015-26698	Facility Type Pipeline
Surface Owner Federal	Mineral Owner Federal	Lease No.

LOCATION OF RELEASE


Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
J	1	22S	31E	2400'	South	1980'	East	Eddy

Latitude 32.42030 Longitude 103.70867

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 50 B/PW	Volume Recovered 0 B/PW
Source of Release Pipeline	Date and Hour of Occurrence 6/1/2009; PM	Date and Hour of Discovery 6/2/2009; AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher/NMOCD	
By Whom? Robert Asher/Yates Petroleum Corporation	Date and Hour 6/3/2009; PM (Voicemail & E-mail)	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	
If a Watercourse was Impacted, Describe Fully.* N/A		
Describe Cause of Problem and Remedial Action Taken.* Pipeline pressured up and ruptured (this release occurred 0.4 miles south of the YPC's Unocal AH U Federal #1 Battery, API Number is for the Unocal AH U Federal #1). Shut wells in, isolated line.		
Describe Area Affected and Cleanup Action Taken.* An approximate area of 60' X 45'. Repaired line. Vertical and horizontal delineation samples will be taken and analysis ran for TPH & BTEX. If initial analytical results for TPH & BTEX are under RRAL's a Final Report, C-141 will be submitted to the OCD requesting closure. Depth to Ground Water: >100' (approx. 448', per the NM Office of the State Engineer), Wellhead Protection Area: No, Distance to Surface Water Body: >1000', SITE RANKING IS 0.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		

OIL CONSERVATION DIVISION

Signature: 	Approved by District Supervisor:	
Printed Name: Robert Asher	Approval Date:	Expiration Date:
Title: Environmental Regulatory Agent	Conditions of Approval:	
E-mail Address: boba@yatespetroleum.com	Attached <input checked="" type="checkbox"/>	
Date: Tuesday, June 09, 2009	Phone: 505-748-4217	

REMEDATION per OCD Rules and
Guidelines. **SUBMIT REMEDIATION**
PROPOSAL BY: 7/23/09

2BP-321

* Attach Additional Sheets If Necessary

Bratcher, Mike, EMNRD

From: Bratcher, Mike, EMNRD
Sent: Tuesday, June 23, 2009 2:55 PM
To: 'Bob Asher'
Subject: Livingston Ridge Water System Release

Bob,

This release that occurred on 6/1/09 (Discovery date: 6/2/09) is being tracked under API # 30-015-26698 and has been assigned admin permit # **2RP-321**.

NMOCD District 2 office is in receipt of the Final Report C-141 submitted for this release. Some clarification is requested regarding the Chain of Custody document from the lab. A note on the document indicates some head space present in the samples. It appears to have been crossed out. Please confirm whether or not the sample containers contained head space or not. Also noted was the temperature of the samples upon receipt by the lab. The temperature is elevated for BTEX samples.

In addition, it was noted that the samples submitted were tested for chloride constituents. The analyses for the chlorides was not submitted with the closure request. Closure for this site cannot be approved at this time without a review of the chloride analyses. Please submit this analytical data for OCD review not later than June 26, 2009.

NOTE: The Final Report C-141 will not be denied at this time, but will be held pending a review of the data.

Thank you,

Mike Bratcher
NMOCD District 2
575-748-1283 Ext.108