

District I  
1625 N. French Dr., Hobbs, NM 88249  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

**RECEIVED**

JUL 08 2009

**HOBBSOCD**

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

**OPERATOR**

Initial Report  Final Report

Name of Company	NADEL AND GUSSMAN HEYCO, LLC	Contact	Keith Cannon or Tammy R. Link
Address	PO Box 1936, Roswell 88202-1936	Telephone No.	(505) 623-6601
Facility Name	ESWS Disposal Station Tank 1 Fed #2	Facility Type	

Surface Owner	USA	Mineral Owner	State of New Mexico	Lease No.	NMNM63365
---------------	-----	---------------	---------------------	-----------	-----------

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
L	1	18S	32E	1650'	S	990'	W	Lea

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_ API# 301025-30112-00100

**NATURE OF RELEASE**

Type of Release	- 81 bbls of oil	Volume of Release	81 bbls	Volume Recovered	66
Source of Release		Date/Hour of Release	6/29/09 3:30	Date/Hour Discovered	6/30/09 11:05 <input checked="" type="checkbox"/>
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Larry Johnson		
By Whom?	Keith Cannon	Date and Hour	11:00 7/1/09		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*  
  
WATER @ 25'

Describe Cause of Problem and Remedial Action Taken.\*  
Electric power outage and knocked water pump out and caused the water to over flow in tank.

Describe Area Affected and Cleanup Action Taken.\*  
Cleanup was completed on 7/2/09 with 800 gallons of fresh water and 25 gallons of micro-blaze.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Tammy R. Link</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Tammy Link	Approved by District Supervisor:	
Title: Engineering Tech	Approval Date:	Expiration Date:
E-mail Address: tlink@heycoenergy.com	Conditions of Approval:	
Date: 7/7/09 Phone: (505)623-6601	Attached <input type="checkbox"/> IRP-09.7.2218	

\* Attach Additional Sheets If Necessary

*Jeffrey Link*  
07/10/09  
NMOCD-HOBBS  
FGRL0919441871

**DENIED**

- ① DEPTH TO GW IS  $\leq$  25' BGS - EXCAVATION REQUIRED
- ② SOILS ARE STILL CONTAMINATED
- ③ DELINEATION HORIZONTALLY & VERTICALLY NOT PROVIDED