

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

RECEIVED State of New Mexico
Conservation and Natural Resources
SEP 16 2009
HOBBSOCD
Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED
SEP 16 2009
HOBBSOCD

Form C-141
Revised October 10, 2000

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Ruthco Oil, LLC	Contact	Joshua Ruth
Address	PO Box 1212 Eunice, NM 88231	Telephone No.	505-631-0437
Facility Name	Hobbs East San Andres SWD	Facility Type	Disposal System
Surface Owner	Ruthco Oil LLC	Mineral Owner	
		Lease No.	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
F	30	18S	39E	1980	N	2310	W	Lea

Latitude _____ Longitude _____

NATURE OF RELEASE 200 bbls H2O

Type of Release	soil water from disposal	Volume of Release	4 bbls BS&W	Volume Recovered	200 H2O 4 bbls
Source of Release	Busted poly line	Date and Hour of Occurrence	6/8/08	Date and Hour of Discovery	6/8/08
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Josh Ruth		p.m.
By Whom?		Date and Hour			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
WATER @ 82'
poly line busted and about 200 bbls water and 4 bbls of BS&W went on ground - sent a crew to fix the poly line, a truck to pick up the water and a backhoe will be sent to clean up and haul off the soil -

Describe Area Affected and Cleanup Action Taken.*
land around the busted pipe was affected - the water was cleaned up and the soil will be replaced -

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: Delinda Ruth	Approved by ENV. ENGINEER: District Supervisor: Sherry Solimine	
Printed Name: Delinda Ruth	Approval Date: 09/17/09	Expiration Date: 11/17/09
Title: Office Manager	Conditions of Approval: DELWATER TO CLEAN + 1. SUBMIT FINAL C-141 BY 11/17/09	Attached <input type="checkbox"/>
E-mail Address: druth@cdservices.com	Date: 6/10/08 Phone: 631-2603	IRP-09, 8-2277

Attach Additional Sheets If Necessary

FOR LOG 26033305

To: Sylvia or Larry Johnson
From: Delinda Ruth, Ruthco Oil, LLC

If you have any questions please call me at 631-2603