

GW - 066

INSPECTION

(Drain-lines, Sump, BGT, Site, etc.)

Lowe, Leonard, EMNRD

From: Lowe, Leonard, EMNRD
Sent: Friday, September 25, 2009 11:09 AM
To: 'Mark Sikelianos'
Subject: GW-066, Espejo CS Inspection
Attachments: GW-066, Inspection Letter.pdf; GW-066, Inspection Photos.pdf

Mr. Sikelianos,

Call me for questions.

llowe

Leonard Lowe

Environmental Engineer
Oil Conservation Division/EMNRD
1220 S. St. Francis Drive
Santa Fe, N.M. 87505
Office: 505-476-3492
Fax: 505-476-3462
E-mail: leonard.lowe@state.nm.us
Website: <http://www.emnrd.state.nm.us/ocd/>



New Mexico Energy, Minerals and Natural Resources Department

Bill Richardson

Governor
Joanna Prukop
Cabinet Secretary

Mark Fesmire
Division Director
Oil Conservation Division



September 25, 2009

Mr. Mark Sikelianos,

**Re: Inspection Report, GW-066
Espejo Compressor Station, New Mexico Gas Company
Sandoval County, New Mexico**

Dear Mr. Sikelianos:

The Oil Conservation Division (OCD) performed an onsite inspection of New Mexico Gas Company's Espejo Compressor Station located in Section 31, Township 12 North, Range 2 West, NMPM, Sandoval County, New Mexico on September 22, 2009.

The facility is in overall good condition and is adhering to its current discharge plan permit, GW-066. Below are highlights of the inspection (reference photos in attachment):

1. **Photos 1 – 2:** Two 70 barrel below-grade tanks were identified at the facility. The leak detection for both was verified dry. Good condition.
2. **Photo 3 - 4:** OCD was made aware of these subgrade bullet tanks identified as "Peter" tanks that receive drainage from the compressor engine rump vents. Owner/Operator shall monitor the status of these tanks. A record should be kept on site to verify integrity of these tanks.
3. **Photo 5 – 6:** One of the skids containing the compressor located on the southeast corner of the building has a cracked. Owner/Operator shall repair this integrity flaw.

OCD appreciates the Owner/Operator's efforts in maintaining a best management facility. If there are any questions pertaining to the inspection, please do not hesitate to contact me at (505) 476-3492 or leonard.lowe@state.nm.us.

Sincerely,

Leonard Lowe
Environmental Engineer/Permit

xc: OCD District III Office, Aztec





Photo 1: Two 70 BBL below-grade tanks.




Photo 2: Verified dry leak detection systems for both.




Photo 3: One of four "Peter" tanks.



Photo 4: More "Peter" tanks.

OCD Inspection: NM Gas Company Espejo CS., GW - 066

Inspector(s): Leonard Lowe

Company Rep: Mark Sikelianos and Mark Vice

Date: 09.22.09

Time: 9:40 – 11:00

Page 2




Photo 5: Cement skid.



Photo 6: Cracked noted in skid.