

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

RECEIVED

SEP 14 2009

HOBBSOCD

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: Southern Union Gas Services	Contact: Rose Slade	
Address: 1507 W. 15 <sup>th</sup> Monahans, Texas 79756	Telephone No.: 432-943-1100 ext. 1116	
Facility Name: Monahans Field Office	Facility Type: Natural Gas Gathering	
Surface Owner: Southern Union Gas Services	Mineral Owner	Lease No.

LOCATION OF RELEASE

Unit Letter N	Section 36	Township 23	Range 36	Feet from the	North/South Line	Feet from the	East/West Line	County Lea
------------------	---------------	----------------	-------------	---------------	------------------	---------------	----------------	---------------

Latitude 32 15.426 Longitude 103 13.647

NATURE OF RELEASE

Type of Release: Crude oil, Produced water, and Natural Gas	Volume of Release: Unknown at this time	Volume Recovered: 0
Source of Release: 24" Pipeline	Date and Hour of Occurrence: not known	Date and Hour of Discovery: 9/15/09 at 10:46:00 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Notified OCD (Hobbs) left message at 11:10 am and Buddy Hill at the NMOCD office Hobbs, NM called me back at 2:20 pm	
By Whom? Rose Slade	Date and Hour: 9/15/09 at 2:20 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

GW 81142

Describe Cause of Problem and Remedial Action Taken.\*

The 24" natural gas gathering line operating at approximately 50 p.s.i. developed a leak. The leak area was excavated and the 24" natural gas line was clamped and left in service.

Describe Area Affected and Cleanup Action Taken.\*

Approximately 45' wide x 65' long of pasture land was excavated by the leak. Final remediation will follow the NMOCD recommended guidelines for leaks and spills.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Rose L. Slade		OIL CONSERVATION DIVISION	
Printed Name: Rose L. Slade		ENV. ENGINEER: Approved by District Supervisor: <i>Jeffrey Lebrun</i>	
Title: EHS Compliance Specialist		Approval Date: 09/15/09	Expiration Date: 11/16/09
E-mail Address: rose.slade@sug.com		Conditions of Approval: DELINEATE TO CLEAN + 1. SUBMIT FINAL C-141 BY 11/16/09.	
Date: 9/14/09	Phone: 432-940-5147	Attached <input type="checkbox"/> IRP-09.10.2305	

\* Attach Additional Sheets If Necessary

FGRL 0928949136