

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico **RECEIVED**
Energy Minerals and Natural Resources
Oil Conservation Division **APR 27 2010**
1220 South St. Francis Dr. **HOBBSUCD**
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

Initial Report

Final Report

Name of Company Apache Corporation	Contact Natalie Gladden
Address P.O. Box 1849, Eunice NM 88231	Telephone No. 575-390-4186
Facility Name Elliott B-17 Battery (Elliott B17 #2)	Facility Type Production Facility

Surface Owner Strain	Mineral Owner BLM/NMOCD	Lease No. 30-025-24864
----------------------	-------------------------	------------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	17	22S	37E	330	North Line	330	East Line	Lea

Latitude _____ Longitude _____

WTR 70'

NATURE OF RELEASE

Type of Release Hydrocarbons	Volume of Release 73bbls	Volume Recovered 50bbls
Source of Release Vandalism	2/16/09 unknown	2/16/09 740am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Larry Johnson	
By Whom? Natalie Gladden	Date and Hour 2/16/09 10:11	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.* Someone unknown shot holes both in our oil tanks and water tanks. The water tank levels were low enough that no produced water was released. All fluid was contained inside the bermed battery. Vacuum trucks were called out to recover fluid. And incident is under investigation with the Lea County Sheriff's Department.

Describe Area Affected and Cleanup Action Taken.*
A Risked Base Closure is submitted with this final C141.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Natalie Gladden</i>	<u>OIL CONSERVATION DIVISION</u>	
Printed Name: Natalie Gladden	<i>Larry Johnson</i> Approved by District Supervisor ENVIRONMENTAL ENGINEER	
Title: EH&S Environmental Tech	Approval Date: <i>4.28.10</i>	Expiration Date:
E-mail Address: natalie.gladden@apachecorp.com	Conditions of Approval:	Attached <input type="checkbox"/> <i>IRP# 09.2.2009</i>
Date: <i>2/16/09</i> 3-11-10 Phone: 575-390-4186		

Attach Additional Sheets If Necessary



RECEIVED
APR 27 2010
HOBBSOCD

Elliott B-17 Battery
Nearest well (Elliott B17 #2)

Lea County
Unit A, S17, T22S, R37E
330' FNL and 330' FEL
API# 30-025-24864
IRP#09-2-2089

Release Date: 02/16/09

Prepared by: Natalie Gladden
Apache Corporation

Dear Larry,

Attached you will find a copy of the original C141, Final C141 and the Risk Based Closure (RBC) for the release on 02/16/09.

With this information that is provided, Apache Corporation respectfully requests your review and approval of the Closure Document for the oil releases that occurred at the Apache Elliott B17 Battery.

If you have any questions or concerns, please feel free to contact me at anytime.

Sincerely,

Natalie Gladden

EH&S Environmental Tech

Permian West and South Districts

The purpose of this report is to document the clean up activities and present supportin information to the NMOCD, requesting a Risk Base Closure of the referenced oil release incident in accordance with the guidelines for Remediation of Leaks, Spills and Releases.

On February 16th 2009, an unknown subject had shot holes both in our oil tanks and our water tanks. The water tank levels were low enough that no produced water was released. All fluid was contained inside the bermed battery. A total of 73bbls of oil was released and 50bbls of total fluid was recovered. The Lea County Sheriff's Department arrived at the scene to perform an investigation. Unfortunatly the suspect was never found.

All of the contamination was hand dug from inside this unlined battery to a total depth of 2' from surface. The contamination was hauled to Sundance Disposal and the battery was backfilled with caliche and pea gravel.

Based on the facts and the event of abandoning this facility in the future, Apache Corporation would like to respectfully request that the NMOCD grant a temporary closure of this facility until further notice of abandoning the battery.

District I
1625 N. French Dr , Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
S. St Francis Dr , Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

FEB 19 2009

HOBBSOCD

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

Initial Report

Final Report

Name of Company Apache Corporation	Contact Natalie Gladden
Address P.O. Box 1849, Eunice NM 88231	Telephone No. 575-390-4186
Facility Name Elliott B-17 Battery (Elliott B17 #2)	Facility Type Production Facility

Surface Owner Strain	Mineral Owner BLM/NMOCD	Lease No. 30-025-24864
----------------------	-------------------------	------------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	17	22S	37E	330	North Line	330	East Line	Lea

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release Hydrocarbons	Volume of Release 73bbls	Volume Recovered 50bbls
Source of Release Vandalism	2/16/09 unknown	2/16/09 740am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Larry Johnson	
By Whom? Natalie Gladden	Date and Hour 2/16/09 10:11	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

Was a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*: Someone unknown shot holes both in our oil tanks and water tanks The water tank levels were low enough that no produced water was released. All fluid was contained inside the bermed battery. Vacuum trucks were called out to recover fluid. And incident is under investigation with the Lea County Sheriff's Department.

Describe Area Affected and Cleanup Action Taken.*
All hydrocarbon impacted soil will be hauled to Sundance Disposal. NMOCD/BLM guidelines will be followed to final closure.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Natalie Gladden</i>	OIL CONSERVATION DIVISION	
Printed Name: Natalie Gladden	<i>L. Johnson</i> Approved by District Supervisor ENVIRONMENTAL ENGINEER	
Title: EH&S Environmental Tech	Approval Date: 2.19.09	Expiration Date: 4.19.09
E-mail Address: natalie.gladden@apachecorp.com	Conditions of Approval:	Attached <input type="checkbox"/> IRP#
Date: 2/16/09 Phone: 575-390-4186	SUBMIT FINAL C-141 w/DOCS	09.2.2089

Attach Additional Sheets If Necessary

RECEIVED

FEB 19 2009

HOBBSOCD