

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

RECEIVED
APR 27 2010
HOBBS OGD

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company Apache Corporation	Contact Natalie Gladden
Address P.O. Box 1849 Eunice, NM 88231	Telephone No. 575-390-4186
Facility Name LM Lambert Bty (Closest well #10)	Facility Type Production
Surface Owner State (leased to Red Byrd)	Mineral Owner Apache
Lease No. 30-025-05934	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
G	6	20S	37E	2310	FNL	1980	FEL	Lea

Latitude _____ Longitude _____

WTR 25'

NATURE OF RELEASE

Type of Release Hydrocarbon	Volume of Release 35bbls	Volume Recovered 30bbls
Source of Release Valve	Date and Hour of Occurrence 6/5/09 4:35pm	Date and Hour of Discovery 6/5/09 4:35pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Left message on weekend phone, then called Larry Johnson	
By Whom? Natalie Gladden	Date and Hour 6/8/09 7:30am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

Valve did not hold at battery, releasing approx 35bbls of oil inside the dyked area. Leak was isolated and repaired. Emergency one call was placed and contamination has started to be excavated.

Describe Area Affected and Cleanup Action Taken.*

A Risk Base Closure was agreed upon by Larry Johnson, to finalize remediation of this facility when this battery is abandoned. 8" on contaminated soil was hauled to Sundance Services.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Natalie Gladden</i>	OIL CONSERVATION DIVISION	
Printed Name: Natalie Gladden	<i>L Johnson</i> Approved by District Supervisor ENVIRONMENTAL ENGINEER	
Title: EH&S Environmental Tech	Approval Date: 4-28-10	Expiration Date: _____
E-mail Address: natalie.gladden@apachecorp.com	Conditions of Approval:	
Date: 02/15/10 Phone: 575-390-4186	Attached <input type="checkbox"/> IRP# 09.6. 2220	

* Attach Additional Sheets If Necessary

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED
JUN 30 2009
HUBBSOCD

Form C-141
Revised October 10, 2003
Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company Apache Corporation	Contact Natalie Gladden
Address P.O. Box 1849 Eunice, NM 88231	Telephone No. 575-390-4186
Facility Name LM Lambert Bty (Closest well #10)	Facility Type Production

Surface Owner State (leased to Red Byrd)	Mineral Owner Apache	Lease No. 30-025-05934
------------------------------------------	----------------------	------------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
G	6	20S	37E	2310	FNL	1980	FEL	Lea

Latitude 32/36.393N Longitude 103/17.238W

WTR 25'

NATURE OF RELEASE

Type of Release Hydrocarbon	Volume of Release 35bbls	Volume Recovered 30bbls
Source of Release Valve	Date and Hour of Occurrence 6/5/09 4:35pm	Date and Hour of Discovery 6/5/09 4:35pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Left message on weekend phone, then called Larry Johnson	
By Whom? Natalie Gladden	Date and Hour 6/8/09 7:30am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
Valve did not hold at battery, releasing approx 35bbls of oil inside the dyked area. Leak was isolated and repaired. Emergency one call was placed and contamination has started to be excavated.

Describe Area Affected and Cleanup Action Taken.*
The hydrocarbon impacted soil will be excavated and hauled to Sundance Services. NMOCD rules and regulations will be followed to closure.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Natalie Gladden</i>	OIL CONSERVATION DIVISION <i>L. Johnson</i>	
Printed Name: Natalie Gladden	Approved by District ENVIRONMENTAL ENGINEER	
Title: EH&S Environmental Tech	Approval Date: <u>6.30.09</u>	Expiration Date: <u>9.1.09</u>
E-mail Address: natalie.gladden@apachecorp.com	Conditions of Approval:	Attached <input type="checkbox"/> IRP# 09.6.222
Date: <u>6/8/09</u> Phone: 575-390-4186		

* Attach Additional Sheets If Necessary

AGRL 0918736668