

06/10/2010 THU 10:49 FAX

FLOYD STEED 575.513.1687

FSTEED@SAMSON.COM

001/002

918.591.7701

FAX 918.591.7727

**District I**

1625 N. French Dr., Hobbs, NM 88240

**District II**

1301 W. Grand Avenue, Artesia, NM 88210

**District III**

1000 Rio Brazos Road, Aztec, NM 87410

**District IV**

1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural ResourcesOil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505Form C-14  
Revised October 10, 2006Submit 2 Copies to a proper  
District Office in accordance  
with Rule 11.5 on back  
side of form**Release Notification and Corrective Action****OPERATOR**☒ Initial Report ☐ Final Report

Name of Company: Samson Resources Company	Contact: Autumn Long
Address: Two West Second Street	Telephone No.: (918) 591-1364
Facility Name: C. S. Caylor	Facility Type: CTB Produced Water Line

Surface Owner: State of New Mexico	Mineral Owner: Samson Resources Company	Lease No.: API #30-02505130
------------------------------------	---	-----------------------------

**LOCATION OF RELEASE**

Unit Letter D	Section 6	Township 17S	Range 37E	Feet from the 660	North/South Line FNL	Feet from the 665	East/West Line FWL	County Lca
------------------	--------------	-----------------	--------------	----------------------	-------------------------	----------------------	-----------------------	---------------

Latitude: 32.86899 N Longitude: -103.29661 W

**NATURE OF RELEASE**

Type of Release: Produced Water	Volume of Release: Unknown Barrels	Volume Recovered: 2 Barrels
Source of Release: Weld in Polyline	Date and Hour of Occurrence: 06/09/2010; Unknown	Date and Hour of Discovery: 06/09/2010; Unknown
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Larry Johnson contacted Autumn Long on 6/9/10, regarding release	
By Whom?	Date and Hour: 06/09/2010; Unknown	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse: N/A	
If a Watercourse was Impacted, Describe Fully.* N/A		

**Describe Cause of Problem and Remedial Action Taken.\***

The release occurred due to a 2" SDR-7 poly line was welded with a SDR-11 poly line, which was incompatible and came apart at the weld, causing a release of an unknown quantity of produced water. Well was shut-in and poly line repaired; two barrels of produced water was vacuumed-up. Further corrective actions are being identified.

**NOTE: SECOND LEAK (X) SAME LOCAL - SEE RP 2553****Describe Area Affected and Cleanup Action Taken.\***

Area affected is approximately 4' x 6'. Two (2) barrels of produced water were vacuumed-up.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rule and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Autumn M. Long</i>	<b>OIL CONSERVATION DIVISION</b> <i>L. Johnson</i>	
Printed Name: Autumn Long	Approved by District <b>ENVIRONMENTAL ENGINEER</b>	
Title: Environmental Specialist	Approval Date: 6.10.10	Expiration Date: 7.8.10.10
E-mail Address: autumnl@samson.com	Conditions of Approval:	
Date: June 9, 2010 Phone: (918) 591-1364	SUBMIT FINAL C-141 w/ Dec BY 10.6.2557	

\* Attach Additional Sheets If Necessary

NLWT 2531

PLWT 3519