

District I  
1625 N French Dr, Hobbs, NM 88240  
District II  
1301 W Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised June 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: Latigo Petroleum, Inc.	Contact: Pat Ellis
Address: P.O. Box 10340 Midland, Texas 79702-7340	Telephone No. (432) 685-8229
Facility Name: Central Corbin Queen Unit	Facility Type: Tank Battery

Surface Owner State of New Mexico	Mineral Owner State of New Mexico	Lease No.
-----------------------------------	-----------------------------------	-----------

WELL # 205

API 30.025.29453

LOCATION OF RELEASE

Unit Letter K	Section 4	Township 18S	Range 33E	Feet from the	North/South Line	Feet from the	East/West Line	County Lea
------------------	--------------	-----------------	--------------	---------------	------------------	---------------	----------------	---------------

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

NATURE OF RELEASE

Type of Release Oil Spill	Volume of Release 35 BO	Volume Recovered None
Source of Release Tank Battery	Date and Hour of Occurrence 06/20/07	Date and Hour of Discovery 06/20/07
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Gary Wink	
By Whom? Bill Hearn	Date and Hour 06/20/07 @ 3:45 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.* None		

Tank spill ran over. Most was contained in the firewall. There was an area 60' x 20' affected outside the firewall. Backhoe utilized to clean up. Area within tank battery scrapped.

Describe Area Affected and Cleanup Action Taken. Highlander was onsite to delineate utilizing a hand auger. On June 25, 2007 approximately 1 foot of soils were excavated and removed from the areas around auger holes AH-1 to AH-3.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Pat Ellis</i>	OIL CONSERVATION DIVISION <i>Johnson</i>	
Printed Name: Pat Ellis	Approved by District SUPERVISOR ENVIRONMENTAL ENGINEER	
Title: EH&S Supervisor	Approval Date: 11.9.07	Expiration Date: _____
E-mail Address: ellisp@pogoproducing.com	Conditions of Approval:	1 RP# Attached <input type="checkbox"/> 1441
Date: _____ Phone: (432) 685-8100		

\* Attach Additional Sheets If Necessary