

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED
NOV 22 2010
NMOCD ARTESIA

Form C-141
Revised October 10, 2003
Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

NMLB/10327 28595

OPERATOR

Initial Report Final Report

Name of Company Yates Petroleum Corporation	OGRID Number 25575	Contact Amanda Trujillo
Address 104 S. 4 TH Street	Telephone No. 575-748-1471	
Facility Name Santa Fe Land SWD #1	API Number 30-015-20501	Order Number 2RP- <i>483</i>

Surface Owner Federal	Mineral Owner Federal	Lease No.
--------------------------	--------------------------	-----------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
I	17	19S	26E	1980	South	660	East	Eddy

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release Water	Volume of Release 80	Volume Recovered 25
Source of Release Gasket Failure on flange connection	Date and Hour of Occurrence 11/19/09 AM <i>11/11/10</i>	Date and Hour of Discovery 11/19/2009 - AM <i>11/11/10</i>
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	IF YES, To Whom? Mike Bratcher - NMOCD/Artesia	
By Whom? Robert Asher - Yates Petroleum Corporation	Date and Hour 11/11/2010 pm <i>3:34P</i>	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	IF YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted, Describe Fully.*
N/A

Describe Cause of Problem and Remedial Action Taken.*

Buried discharge line off of pump leaked. The pump was shut down and the valves to tanks were shut. A vacuum truck was then dispatched to pick up any standing fluids.

Describe Area Affected and Cleanup Action Taken.*

An approximate size of 20' x 60' was impacted. The impacted area is located within the berm. A one call has been made and work will begin to excavate contaminated material and replace the buried line with a surface line. Soil from the pooling areas was excavated and disposed of at an NMOCD approved facility. **Depth to Ground Water: >100' (approx. 116', per New Mexico Office of the State Engineer); Wellhead Protection Area: No; Distance to Surface Water Body: >1000'; SITE RANKING IS 0. Based on site ground water quality and enclosed analytical results.** *SEE NOTE*

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: *A Trujillo*
Printed Name: Amanda Trujillo
Title: Environmental Scientist
E-mail Address: atrujillo@yatespetroleum.com
Date: Friday, November 19, 2010 Phone: 575-748-4310

OIL CONSERVATION DIVISION
Signed By: *Mike Bratcher*
Approved by District Supervisor:
Approval Date: *NOV 23 2010* Expiration Date:
Conditions of Approval:
REMEDATION per OCD Rules and Guidelines. **SUBMIT REMEDIATION PROPOSAL BY: 12/23/2010**
Attached

* Attach Additional Sheets If Necessary

*NOTE: No water quality data or analytical submitted with this form
Remediation proposal to be based on contaminant delimitation*

2RP-483

Bratcher, Mike, EMNRD

From: Amanda Trujillo [atrujillo@yatespetroleum.com]
Sent: Monday, November 22, 2010 3:58 PM
To: Bratcher, Mike, EMNRD
Subject: Santa Fe Land SWD C-141
Attachments: Santa Fe Land SWD 1(11-19-2010 Initial).pdf

Attached is the C-141 for a release reported to you at the Santa Fe Land SWD by Bob Asher on 11/11/2010.

Amanda N. Trujillo
Environmental Scientist
Yates Petroleum Corporation
Office 575-748-4310
Cell 575-703-6537
Email atrujillo@yatespetroleum.com

Bratcher, Mike, EMNRD

From: Bob Asher [BobA@yatespetroleum.com]
Sent: Thursday, November 11, 2010 3:34 PM
To: Bratcher, Mike, EMNRD
Cc: Jerry Fanning
Subject: Release (Santa Fe Land SWD #1)

Mike,

Yates Petroleum Corporation is reporting a release at the following location that occurred Thursday, November 11, 2010.

Santa Fe Land SWD #1
30-015-20501
Section 17, T19S-R26E
Eddy County, New Mexico

Released: 80 B/PW

A vacuum truck was called, no further information at this time.

A C-141 report will be submitted with complete information.

Thank you.



Robert Asher
Yates Petroleum Corporation
boba@yatespetroleum.com
575-748-4217 (Office)
575-365-4021 (Cell)
575-748-4662 (Fax)