


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003
Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

AKMW 1035725961

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	COG OPERATING LLC 229137	Contact	Pat Ellis
Address	550 W. Texas, Suite 100, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	GJ WEST COOP UNIT #125	Facility Type	Well (Flowline)

Surface Owner	State	Mineral Owner	Lease No. API# 30-015-03163
---------------	-------	---------------	-----------------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	28	17S	29E					Eddy

Latitude 32 48.015 Longitude 104 04.276

2 RP-526

NATURE OF RELEASE

Type of Release	Produced Fluids	Volume of Release	50bbls	Volume Recovered	0bbls
Source of Release	Flowline	Date and Hour of Occurrence	06/24/2010	Date and Hour of Discovery	06/24/2010 1:00 p.m.
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher—OCD		
By Whom?	Josh Russo	Date and Hour	06/25/2010 9:19 a.m.		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

The cause of this release was due to a ruptured flowline. The flowline has been repaired and put back into service.

Describe Area Affected and Cleanup Action Taken.*

The ruptured GJ West Coop #125 flowline released 50bbls of produced fluids into the pasture and we were not able to recover any fluid with a vacuum truck. The dimensions of the spill area are 750' long and no greater than 15' wide. (The closest well location to the release site is the GJ West Coop Unit #4, which is 150' northwest of the spill site, API # 30-015-03173, Unit P, Sec. 28-T17S-R29E, 990 FSL 330 FEL, Eddy County, NM, GPS 32.80096 - 104.07228) Tetra Tech will sample the spill site area to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:		OIL CONSERVATION DIVISION	
Printed Name:	Josh Russo	Approved by District Supervisor	Signed By: Mike Bratcher
Title:	HSE Coordinator	Approval Date:	1/19/2011
E-mail Address:	jrusso@conchoresources.com	Expiration Date:	
Date:	06/28/2010	Phone:	432-212-2399
		Conditions of Approval:	Remediation per NMOCD rules & Guidelines
		Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary

Remediation proposal approved
1/19/2011
2 RP-526

Bratcher, Mike, EMNRD

From: Joshua Russo [jrusso@conchoresources.com]
Sent: Monday, June 28, 2010 10:34 AM
To: Bratcher, Mike, EMNRD
Cc: Pat Ellis; Tavarez, Ike
Subject: GJ West Coop Unit #125 C-141 Initial Report
Attachments: GJ WEST COOP UNIT #125 -- DATE OF RELEASE -- 06-24-2010.PDF

Mr. Bratcher,

Please find enclosed the C-141 Initial Report for the GJ West Coop Unit #125 flowline release that we had on 06/24/2010. If you have any questions or concerns please do not hesitate to contact me.

Thank you,

Joshua Russo

HSE Coordinator
550 W. Texas Ave, Suite 100
Midland, Texas 79701
Phone: (432) 683-7443
Cell: (432) 212-2399
jrusso@conchoresources.com



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

Bratcher, Mike, EMNRD

From: Joshua Russo [jrusso@conchoresources.com]
Sent: Friday, June 25, 2010 8:19 AM
To: Bratcher, Mike, EMNRD
Cc: Pat Ellis; Rick Wright; Tavarez, Ike
Subject: GJ West Coop #125 flowline leak immediate notification

Mr. Bratcher,

Please see below the details to a release that we had on 06/24/2010 at 1:00 p.m. originating from the flowline coming from the GJ West Coop #125 well. We will follow up with a C-141 Initial Report within 15 days of the release date. If you have any questions or comments please feel free to contact me.

Thank you,

Joshua Russo

HSE Coordinator
550 W. Texas Ave, Suite 100
Midland, Texas 79701
Phone: (432) 683-7443
Cell: (432) 212-2399
jrusso@conchoresources.com



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

From: Rick Wright
Sent: Thursday, June 24, 2010 8:03 PM
To: Pat Ellis; Joshua Russo
Cc: Ron Beasley; Kent Greenway; Gail Lamb
Subject: GJ West flowline leak

On 6-24-10 at 1:00pm, a flowline leak was reported on the GJ West COOP unit #125 flowline. This leak occurred entirely in the pasture. Approximately 50 bbls was released, none recoverable. The spill area is approximately 750' long never getting over 15' wide. We will take no action until instructed to do so. Legal description below.

Closest well (150' NW of spill site)
GJ West COOP Unit #4
S/E 4 S/E 4
Sec.28-T17S-R29E

Spill Site
N 32* 48.015
W 104* 04.276

Thanks,

Rick Wright
Production Foreman
COG Operating, LLC
2407 Pecos Ave.
Artesia, NM 88210
575.746.2010 office
432.528.5363 cell
575.746.2096 fax
rwright@conchoresources.com



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.