

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

FEB 01 2011

NMOCD ARTESIA

Form C-141
Revised October 10, 2003

Supply 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☒ Final Report

Name of Company	COG OPERATING LLC 229/37	Contact	Pat Ellis
Address	550 W. Texas, Suite 100, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	Myox 21 State Com #8H	Facility Type	Tank Battery

Surface Owner	State	Mineral Owner		Lease No. (API#)	30-015-37034
---------------	-------	---------------	--	------------------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	21	25S	28E					Eddy

Latitude 32 07.229 Longitude 104 05.967

NATURE OF RELEASE

Type of Release	Oil	Volume of Release	110bbls	Volume Recovered	108bbls
Source of Release	2" drain line at oil tank	Date and Hour of Occurrence	01/24/2011	Date and Hour of Discovery	01/24/2011
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher—OCD		
By Whom?	Josh Russo	Date and Hour	01/25/2011 2:53 p.m.		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

Oil was placed into a new tank where the 2" drain valve was left open. The drain valve has been closed.

Describe Area Affected and Cleanup Action Taken.*

Initially 110bbls of oil was released from the 2" drain valve at the oil tank and we were able to recover 108bbls with a vacuum truck. All released oil was completely contained inside the facility berm wall which is lined with 40mil plastic. The spill area measured 30' x 60' inside the dike. All contaminated gravel was removed and disposed appropriately. Additional gravel was added to the facility as necessary. The facility has been restored to its prior condition.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:				OIL CONSERVATION DIVISION	
Printed Name:	Josh Russo			Approved by District Supervisor: 	
Title:	HSE Coordinator			Approval Date:	3/2/2011
E-mail Address:	jrusso@conchoresources.com			Expiration Date:	N/A
Date:	02/01/2011	Phone:	432-212-2399	Conditions of Approval:	N/A
				Attached	<input type="checkbox"/>

* Attach Additional Sheets If Necessary

2RP-596

Bratcher, Mike, EMNRD

From: Joshua Russo [jrusso@conchoresources.com]
Sent: Tuesday, February 01, 2011 9:41 AM
To: Bratcher, Mike, EMNRD
Cc: Pat Ellis
Subject: C-141 - Myox 21 State Com #8H Initial/Final Report
Attachments: MYOX 21 STATE COM #8H -- DATE OF RELEASE -- 01-24-2011.PDF

Mr. Bratcher,

Please see attached the C-141 Initial/Final Report for a release we had on 01/24/2011 at the Myox 21 State Com #8H TB, which is a lined facility.

Thank you,

Joshua Russo

HSE Coordinator
550 W. Texas Ave, Suite 100
Midland, Texas 79701
Phone: (432) 683-7443
Cell: (432) 212-2399
jrusso@conchoresources.com



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

Bratcher, Mike, EMNRD

From: Joshua Russo [jrusso@conchoresources.com]
Sent: Tuesday, January 25, 2011 1:53 PM
To: Bratcher, Mike, EMNRD
Cc: Pat Ellis
Subject: MYOX 21 State Com #8H Immediate Notification

Mr. Bratcher,

Please see below the details to a release that occurred in a lined facility on 01/24/2011. I will follow up with a C-141 Initial/Final Report Form.

On 1-24-11 at 4:00pm a spill occurred at the Myox 21 St. Com. #8H. A 2" drain valve was inadvertently left open on a new oil tank. Oil placed in the tank ran out into the dike, which is lined with 40mil plastic. 110bbls of oil was released and 109bbls were recovered. All fluids were removed and the contaminated gravel will be removed and replaced with fresh gravel as needed.

GPS coordinates, Legal description, and driving directions below:

N 32* 07.229 W 104* 05.967

Myox 21 State Com. #8H

660' FNL & 330' FWL

Sec.21-T24S-R28E

Eddy County, NM

API #30-015-37034

Thanks,

Joshua Russo

HSE Coordinator

550 W. Texas Ave, Suite 100

Midland, Texas 79701

Phone: (432) 683-7443

Cell: (432) 212-2399

jrusso@conchoresources.com



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.