


District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

**NMOCD**  
State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505



Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

30-015-31990  
NKMW 1035733871

**OPERATOR**

☒ Initial Report ☐ Final Report

Name of Company BOPCO, L.P. 260737	Contact Tony Savoie
Address 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 432-556-8730
Facility Name Poker Lake Unit Delaware C Tank Battery	Facility Type E&P

Surface Owner Federal	Mineral Owner Federal	Lease No.
-----------------------	-----------------------	-----------

**LOCATION OF RELEASE**

Unit Letter G	Section 6	Township 24S	Range 30E	Feet from the	North/South Line	Feet from the	East/West Line	County Eddy
------------------	--------------	-----------------	--------------	---------------	------------------	---------------	----------------	----------------

Latitude N 32.248735 Longitude W 103.918671

**NATURE OF RELEASE**

Type of Release: Produced water and crude oil	Volume of Release: 320 Bbls of Produced water and 8 Bbls of Crude oil	Volume Recovered: 300 bbls of produced water and 8 bbls crude oil
Source of Release: 300 bbl produced water tank overflow	Date and Hour of Occurrence Unkown	Date and Hour of Discovery 5/13/10 8:00 a.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Randy NMOCD on call operator	
By Whom? Tony Savoie	Date and Hour 5/13/10 10:21 a.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\* The produced water tank overflowed due to a pump malfunction. The main water transfer pump failed to come. The pump was re-set.

Describe Area Affected and Cleanup Action Taken.\* The released fluid affected an area of approximately 6700 sq. ft inside the earthen containment around the tanks. The free standing fluids were removed. An area inside the containment area was sampled on 5/24/10 to a depth of approximately 80 ft. Below ground surface, samples were collected at 5 ft. intervals and sampled for TPH, BTEX and Chlorides. Estimated depth to water is thought to be greater than 200 ft. A remediation plan along with a new containment plan will be submitted.


The Site remediation for the produced water and crude oil spill will follow the NMOCD guidelines for leaks and spills.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <u>Tony Savoie</u>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Tony Savoie	Approved by District Supervisor: Signed By <u>Mike Brannan</u>	
Title: Waste Mgmt. & Remediation Specialist	Approval Date: <u>3/3/11</u>	Expiration Date:
E-mail Address: TASavoie@BassPet.com	Conditions of Approval: Remediation per OCD Rules & Guidelines. <b>SUBMIT REMEDIATION</b>	Attached <input type="checkbox"/>
Date: 5/27/10 Phone: 432-556-8730	<b>PROPOSAL NOT LATER THAN:</b> <u>4/3/11</u>	

\* Attach Additional Sheets If Necessary

2 RP-531



1" = 1,066.7 ft      Data Zoom 14-0