

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

FEB 18 2011

NMOCD ARTESIA

Form C-141
Revised October 10, 2003

Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

30-015-20918

AKMW 1105550129

147179 OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	CHESAPEAKE OPERATING, INC.	Contact	BRADLEY BLEVINS
Address	P. O. BOX 190 HOBBS, NM 88241	Telephone No.	575-391-1462
Facility Name	Old Indian Draw Unit 1	Facility Type	Tank Battery
Surface Owner	Mineral Owner	Lease No.	

LOCATION OF RELEASE API #30-015-20918

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
J	18	22S	28E	1980	SOUTH	1980	EAST	EDDY

Latitude Longitude

NATURE OF RELEASE

Type of Release	Produced water	Volume of Release	70 BBLS	Volume Recovered	60 BBLS
Source of Release	Tank valve corroded and broke	Date and Hour of Occurrence	2/17/11 9:00 a.m.	Date and Hour of Discovery	2/17/11 10:00 A.M.
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher		
By Whom?	Bradley Blevins	Date and Hour	2/17/11 3:05 PM		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

Valve to water tank corroded and broke releasing 70 BBLS of produced water into the containment area and onto the location. Vacuum trucks were used to recover free fluids.

Describe Area Affected and Cleanup Action Taken.*

10 BBLS of produced water were lost. Upon completion of delineation and remediation activities a final C-141 and lab data will be furnished to the OCD.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <u>Bradley Blevins</u>	OIL CONSERVATION DIVISION	
Printed Name: Bradley Blevins	Approved by District Supervisor	Signed By <u>Mike Bratcher</u>
Title: HSE Specialist	Approval Date: <u>3/3/11</u>	Expiration Date:
E-mail Address: Bradley.blevins@chk.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 2/18/11 Phone: 575-391-1462	Remediation per OCD Rules & Guidelines. SUBMIT REMEDIATION PROPOSAL NOT LATER THAN: <u>4/3/11</u>	

* Attach Additional Sheets If Necessary

2RP-611

Bratcher, Mike, EMNRD

From: Cliff P. Brunson [cbrunson@bbcinternational.com]
Sent: Friday, February 18, 2011 5:19 PM
To: Bratcher, Mike, EMNRD
Cc: Bradley Blevins; Ken Swinney; Jennifer Gilkey
Subject: Chesapeake-Old Indian Draw Unit No. 1
Attachments: Initial C-141-Old Indian Draw Unit #1.pdf

Mike,

Please find attached the initial C-141 for the above referenced well site release.

Thanks, Cliff

Cliff P. Brunson, CEI, CRS
President
BBC International, Inc.
World-Wide Environmental Specialists
Mailing Address:
P. O. Box 805
Hobbs, NM 88241-0805 USA
Shipping Address:
1324 W. Marland Blvd.
Hobbs, NM 88240 USA
Phone: (575) 397-6388
Fax: (575) 397-0397
E-mail: cbrunson@bbcinternational.com
Web: www.bbcinternational.com

Confidentiality Notice: This electronic transmission (and any attached documents) is intended only for the person(s) to whom it is addressed and may contain information that is privileged, confidential, or otherwise protected from disclosure. If you have received this transmission in error, please immediately notify the sender by e-mail or by collect telephone call to (575) 397-6388 for handling instructions. Any disclosure or distribution of the contents of this transmission by anyone other than the named recipient(s) is strictly prohibited.

Bratcher, Mike, EMNRD

From: Cliff P. Brunson [cbrunson@bbcinternational.com]
Sent: Friday, February 18, 2011 5:28 PM
To: Bratcher, Mike, EMNRD
Cc: Bradley Blevins; Ken Swinney; Jennifer Gilkey; James A. Amos; Terry Gregston
Subject: Chesapeake-Old Indian Draw Unit No. 1
Attachments: Initial C-141-Old Indian Draw Unit #1.pdf

Mike,

Please find attached the initial C-141 for the above referenced well site release.

Thanks, Cliff

Cliff P. Brunson, CEI, CRS
President
BBC International, Inc.
World-Wide Environmental Specialists
Mailing Address:
P. O. Box 805
Hobbs, NM 88241-0805 USA
Shipping Address:
1324 W. Marland Blvd.
Hobbs, NM 88240 USA
Phone: (575) 397-6388
Fax: (575) 397-0397
E-mail: cbrunson@bbcinternational.com
Web: www.bbcinternational.com

Confidentiality Notice: This electronic transmission (and any attached documents) is intended only for the person(s) to whom it is addressed and may contain information that is privileged, confidential, or otherwise protected from disclosure. If you have received this transmission in error, please immediately notify the sender by e-mail or by collect telephone call to (575) 397-6388 for handling instructions. Any disclosure or distribution of the contents of this transmission by anyone other than the named recipient(s) is strictly prohibited.
