

RECEIVED MAY 19 2010

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

30-015-34571

Release Notification and Corrective Action

17KMW 1035538024

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	COG OPERATING LLC 229137	Contact	Pat Ellis
Address	550 W. Texas, Suite 100, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	HARPER STATE #5	Facility Type	TANK BATTERY

Surface Owner	STATE	Mineral Owner		Lease No.	B-936
---------------	-------	---------------	--	-----------	-------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	16	17S	30E					Eddy

Latitude 32 49.715 Longitude 103 58.145

NATURE OF RELEASE

Type of Release	Produced Water	Volume of Release	450bbls	Volume Recovered	450bbls
Source of Release	Water Tank	Date and Hour of Occurrence	05/06/2010	Date and Hour of Discovery	05/07/2010
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher - OCD		
By Whom?	Ronnie Tice	Date and Hour	05/07/2010	5:15 p.m.	
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

The release was caused due to an alarm recognition error.

Describe Area Affected and Cleanup Action Taken.*

450bbls of produced water was initially released and 450bbls was immediately recovered by a vacuum truck. The produced water ran off from the water tank covering an area 20' x 120', then pooled in an area with the dimensions of 75' x 200'. Tetra Tech will sample the spill site area to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD for approval before any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:		OIL CONSERVATION DIVISION	
Printed Name:	Josh Russo	Approved by District Supervisor:	
Title:	HSE Coordinator	Signed By:	
E-mail Address:	jrusso@conchoresources.com	Approval Date:	3/3/11
Date:	05/10/2010	Expiration Date:	
Phone:	432-212-2399	Conditions of Approval:	Attached <input type="checkbox"/>

* Attach Additional Sheets If Necessary

Remediation per OCD Rules &
Guidelines. **SUBMIT REMEDIATION
PROPOSAL NOT LATER THAN:**

4/3/11

2 RP-507

Bratcher, Mike, EMNRD

From: Joshua Russo [jrusso@conchoresources.com]
Sent: Wednesday, May 19, 2010 7:53 AM
To: Bratcher, Mike, EMNRD
Cc: Pat Ellis; Tavaréz, Ike
Subject: C-141 Initial Report - Harper State, GJ West Coop South
Attachments: HARPER STATE #5 TANK BATTERY -- DATE OF RELEASE 05-06-2010.PDF; GJ WEST COOP SOUTH WATER DISTRIBUTION SITE -- DATE OF RELEASE 05-06-2010.PDF

Mike,

Attached are the the C-141 Initial Reports for the Harper State #5 Tank Battery and the GJ West Coop South Water Distribution Site. If you have any questions or concerns please contact me.

Thanks,

Joshua Russo

HSE Coordinator
550 W. Texas Ave, Suite 100
Midland, Texas 79701
Phone: (432) 683-7443
Cell: (432) 212-2399
jrusso@conchoresources.com



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.