

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

AKMW 1103247021

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	COG OPERATING LLC	Contact	Pat Ellis
Address	550 W. Texas, Suite 100, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	SRO SWD #101	Facility Type	SWD

Surface Owner	State	Mineral Owner	Lease No. (API#) 30-015-26105
---------------	-------	---------------	-------------------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
G	5	26	28					Eddy

Latitude 32 04.389 Longitude 104 06.431

NATURE OF RELEASE

Type of Release	Produced water	Volume of Release	180bbbls	Volume Recovered	130bbbls
Source of Release	Water line	Date and Hour of Occurrence	01/22/2011	Date and Hour of Discovery	01/22/2011 3:00 p.m.
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher—OCD		
By Whom?	Josh Russo	Date and Hour	01/24/2011 10:32 a.m.		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

Construction crew tied in water transfer pump at the Myox 31 13 to wrong disposal line causing release. The water transfer pump was hooked up to the appropriate line and returned to service.

Describe Area Affected and Cleanup Action Taken.*

Initially 180bbbls was released from the line and we were able to recover 130bbbls with vacuum trucks. The spill was largely contained on the pad location of the SRO SWD #101 and measured an area of 50' X 80'. Northwest of the location a 3' x 50' stream traveled off of the location and into the pasture. East of the location produced water flowed measuring an area of 4' x 20'. Tetra Tech will sample the spill site area to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Josh Russo		Approved by District Supervisor: 	
Title: HSE Coordinator		Approval Date: 3/3/11	Expiration Date:
E-mail Address: jrusso@conchoresources.com		Conditions of Approval:	
Date: 02/01/2011 Phone: 432-212-2399		Remediation per OCD Rules & Guidelines. SUBMIT REMEDIATION PROPOSAL NOT LATER THAN:	

* Attach Additional Sheets If Necessary

4/3/11

2 RP. 597

Bratcher, Mike, EMNRD

From: Joshua Russo [jrusso@conchoresources.com]
Sent: Monday, January 24, 2011 9:32 AM
To: Bratcher, Mike, EMNRD
Cc: Tavarez, Ike; Pat Ellis
Subject: SRO SWD 101 immediate notification

Mr. Bratcher,

Please see below the details to a release that occurred on 01/22/2011.

On 1-22-11 at 3:00pm a produced water spill was discovered at the SRO 102 SWD. The spill was caused by an improper connection originating at the Myox St. Unit 31 Com. #13 battery. The connection has been repaired and the battery returned to service. Approximately 180bbls was released and 130bbls were recovered. All standing fluid was removed and location will be scraped of contaminants. Most fluids remained on location with the exception of a 3' X 50' area northwest of the location and a 4' X 20' area east of the location.

GPS coordinates, Legal description, and driving directions are as follows:

N 32* 04.389 W 104* 06.431
SRO SWD 101
1980 FNL & 1980 FEL
Sec.5-T26E-R28E
Eddy County, NM
API #30-015-26105

Hwy 285 South of Malaga to mm5, West on White City Rd. 3 miles, South 1 mile, east 0.1 mile.

Thanks,

Joshua Russo

HSE Coordinator
550 W. Texas Ave, Suite 100
Midland, Texas 79701
Phone: (432) 683-7443
Cell: (432) 212-2399
jrusso@conchoresources.com



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

Bratcher, Mike, EMNRD

From: Joshua Russo [jrusso@conchoresources.com]
Sent: Tuesday, February 01, 2011 8:51 AM
To: Bratcher, Mike, EMNRD
Cc: Pat Ellis; Tavarez, Ike; Dorey, Kim; tom.k.franklin@tetrattech.com
Subject: C-141 - SRO SWD #101
Attachments: SRO SWD #101 -- DATE OF RELEASE -- 01-22-2011.PDF

Mr. Bratcher,

Please see attached the C-141 Initial Report for a release we had on 01/22/2011 at the SRO SWD #101.

Thank you,

Joshua Russo

HSE Coordinator
550 W. Texas Ave, Suite 100
Midland, Texas 79701
Phone: (432) 683-7443
Cell: (432) 212-2399
jrusso@conchoresources.com



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.