



# AE Order Number Banner

## Report Description

This report shows an AE Order Number in Barcode format for purposes of scanning. The Barcode format is Code 39.



**App Number:** pKMW1107455430

**2RP - 640**

**COG OPERATING LLC**

3/15/2011

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

RECEIVED

MAR 11 2011

Form C-141  
Revised October 10, 2003

NMOC D ARTESIA  
Submit 3 copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	COG OPERATING LLC 229137	Contact	Pat Ellis
Address	550 W. Texas, Suite 100, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	McIntyre DK Federal #6	Facility Type	Flowline
Surface Owner	Federal	Mineral Owner	
		Lease No. (API#)	30-015-20972

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
N	17	17S	30E					Eddy

Latitude 32.8298 Longitude 103.9947

NATURE OF RELEASE

Type of Release	Oil / Produced water	Volume of Release	20bbls	Volume Recovered	17bbls
Source of Release	Flowline	Date and Hour of Occurrence	03/04/2011	Date and Hour of Discovery	03/04/2011 11:00 a.m.
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?		Date and Hour			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

The flowline developed a leak due to corrosion and was initially clamped to stop the release; The corroded area has since been replaced with a new joint.

Describe Area Affected and Cleanup Action Taken.\*

Initially 20bbls of fluid was released from the flowline and we were able to recover 17bbls of fluid with a vacuum truck. The spill occurred in the pasture roughly 100' East of the Jenkins B Tank Battery. The dimensions of the spill measured 100' x 100'. Tetra Tech will sample the spill site area to delineate any possible contamination from the release and we will present a remediation work plan to the NMOC D / BLM for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOC D rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOC D marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOC D acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	OIL CONSERVATION DIVISION		
Printed Name:	Josh Russo	Approved by District Supervisor:	Signed By <u>Mike Brannon</u>
Title:	HSE Coordinator	Approval Date:	3/15/11
E-mail Address:	jrusso@conchoresources.com	Expiration Date:	
Date:	03/10/2011	Phone:	432-212-2399
		Conditions of Approval:	Attached <input type="checkbox"/>

\* Attach Additional Sheets If Necessary

REMEDATION per OCD Rules and  
Guidelines. SUBMIT REMEDIATION  
PROPOSAL BY:

4/15/11

2RP-640

## Bratcher, Mike, EMNRD

---

**From:** Joshua Russo [jrusso@conchoresources.com]  
**Sent:** Thursday, March 10, 2011 3:57 PM  
**To:** Bratcher, Mike, EMNRD; terry\_gregston@nm.blm.gov  
**Cc:** Pat Ellis; james\_amos@nm.blm.gov; Tavaréz, Ike; Dorey, Kim; tom.k.franklin@tetrattech.com  
**Subject:** C-141 - McIntyre DK Federal #6  
**Attachments:** MCINTYRE DK FEDERAL #6 FLOWLINE -- DATE OF RELEASE -- 03-04-2011.PDF

Please see attached the C-141 Initial Report for a release that occurred on 03/04/2011.

Thanks,

### **Joshua Russo**

HSE Coordinator  
550 W. Texas Ave, Suite 100  
Midland, Texas 79701  
Phone: (432) 683-7443  
Cell: (432) 212-2399  
[jrusso@conchoresources.com](mailto:jrusso@conchoresources.com)



**CONFIDENTIALITY NOTICE:** The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.