

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	COG OPERATING, LLC	Contact	Pat Ellis
Address	550 W. Texas, Suite 100, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	Polaris Federal 1-3 Tank Battery	Facility Type	Tank Battery

Surface Owner	Federal	Mineral Owner		Lease No. (API #)	30-015-31565
---------------	---------	---------------	--	-------------------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
F	17	17S	30E	2310	NORTH	2210	WEST	EDDY

Latitude 32 50.105 Longitude 103 59.751

NATURE OF RELEASE

Type of Release	Produced fluids	Volume of Release	25 bbls	Volume Recovered	15 bbls
Source of Release	Header	Date and Hour of Occurrence	02/15/2010	Date and Hour of Discovery	02/15/2010
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Terry Gregston - BLM		
By Whom?	Ronnie Tice	Date and Hour	02/15/2010		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

The connection from the flowline to the header was defective. The failed header/flowline connection was repaired.

Describe Area Affected and Cleanup Action Taken.*

25 bbls of produced fluid was released at the faulty header connection in the form of free fluid on location or overspray into the pasture. 15 bbls of free fluid was picked up by a vacuum truck. One-call protocol will be made by dirt contractor who will then wait for archeological/ wildlife sensitivity clearance from BLM before removing any saturated soils prior to sampling by Tetra Tech.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:		OIL CONSERVATION DIVISION	
Printed Name:	Josh Russo	Approved by District Supervisor:	
Title:	HSE Coordinator	Approval Date:	3/17/11
E-mail Address:	jrusso@conchoresources.com	Expiration Date:	
Date:	02/17/2010	Conditions of Approval:	Attached <input type="checkbox"/>
Phone:	432-212-2399		

* Attach Additional Sheets If Necessary

REMEDATION per OCD Rules and
Guidelines. SUBMIT REMEDIATION
PROPOSAL BY:

4/17/11

2RP-645

Bratcher, Mike, EMNRD

From: Joshua Russo [jrusso@conchoresources.com]
Sent: Wednesday, February 24, 2010 12:23 PM
To: Bratcher, Mike, EMNRD; james_amos@nm.blm.gov
Cc: terry_gregston@nm.blm.gov; Pat Ellis; Ike Tavaréz (ike.tavaréz@tetrattech.com)
Subject: C-141 Initial Report - Polaris Federal 1-3 Tank Battery
Attachments: POLARIS FEDERAL 1-3 TANK BATTERY.PDF

Attached is the C-141 Initial Report for the Polaris Federal 1-3 Tank Battery. If you have any questions or concerns please do not hesitate to contact me.

Thanks,

Joshua Russo

HSE Coordinator
550 W. Texas Ave, Suite 100
Midland, Texas 79701
Phone: (432) 683-7443
Cell: (432) 212-2399
jrusso@conchoresources.com



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

This inbound email has been scanned for malicious software and transmitted safely to you using Webroot Email Security.
