

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

FEB - 2 2009

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

Release Notification and Corrective Action

*DKMW 1109028533* OPERATOR ☒ Initial Report ☐ Final Report

Name of Company	Tandem Energy Corporation <i>236183</i>	Contact	Dean Mathiews
Address	120 S. Main Street, Suite 350, Victoria, TX 77901	Telephone No.	361-550-2800
Facility Name	Old Loco Battery	Facility Type	Battery
Surface Owner	Mineral Owner	Lease No.	

400' East from Old Loco #11 - API # 30-015-03211 LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
K	32	17S	29E	2310	South	2310	West	Eddy

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

NATURE OF RELEASE

Type of Release: Oil, Produced Water & BS & W	Volume of Release 100 bbls	Volume Recovered 20 bbls
Source of Release: Nipple broke off injection pump	Date and Hour of Occurrence 2:00 p.m. 01/17/09	Date and Hour of Discovery 2:00 p.m. 01/17/09
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher at OCD, Jim Amos, BLM	
By Whom? Brandi Barthels	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

N/A

Describe Cause of Problem and Remedial Action Taken.\*

Nipple Broke off Injection Pump. Initial response taken, gathered affected soil & temporarily placed on bermed 20 mil poly. The remedial action plan will be developed and executed for the site after soil sampling is conducted.

Describe Area Affected and Cleanup Action Taken.\*

Area of spill is 20,350 sq ft. The remediation plan will be developed and executed based upon the soil analysis results.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Dean Mathiew</i>	OIL CONSERVATION DIVISION	
Printed Name: Dean Mathiews	Signed By <i>Mike Bratcher</i>	
Title: Operations Manager	Approved by District Supervisor:	
E-mail Address: dmathiews@platenergy.com	Approval Date: <i>3/31/11</i>	Expiration Date:
Date: 01-27-09 Phone: 361.550-2800	Conditions of Approval:	Attached <input type="checkbox"/>

\* Attach Additional Sheets If Necessary

REMEDATION per OCD Rules and  
Guidelines. SUBMIT REMEDIATION  
PROPOSAL BY:

*5/1/11*

*2RP-679*