

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

JUL 23 2009

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

30-015-30948

Release Notification and Corrective Action

| | | |
|--------------------------------|--|--|
| Name of Company OXY USA | | Contact Kelton Beaird |
| Address 1502 W. Commerce | | Telephone No. (O) 575-628-4121 C) 575-390-1903 |
| Facility Name Jones Canyon 4-6 | | Facility Type Well with Battery |
| Surface Owner BLM | | |
| Mineral Owner | | Lease No. |

LOCATION OF RELEASE



| | | | | | | | | |
|------------------|--------------|-----------------|--------------|---------------|------------------|---------------|----------------|----------------|
| Unit Letter G | Section 4 | Township 22S | Range 24E | Feet from the | North/South Line | Feet from the | East/West Line | County Eddy |
|------------------|--------------|-----------------|--------------|---------------|------------------|---------------|----------------|----------------|

Latitude _____ Longitude _____

NATURE OF RELEASE

| | | |
|--|--|---------------------------------------|
| Type of Release Produced Water | Volume of Release 20 | Volume Recovered 4 |
| Source of Release Thrust Chamber on SWD pump | Date and Hour of Occurrence | Date and Hour of Discovery 7-19-09 |
| Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required | If YES, To Whom? Mike Bratcher (left message) | |
| By Whom? Rick Kerby (HES-Oxy) | Date and Hour See above | |
| Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | If YES, Volume Impacting the Watercourse. | |
| If a Watercourse was Impacted, Describe Fully.* | | |
| Describe Cause of Problem and Remedial Action Taken.* The thrust chamber on the SWD pump was leaking. Vac-truck was called to pick up remaining fluid | | |
| Describe Area Affected and Cleanup Action Taken.* Area affected was on location. Chlorides are approx. 1200ppm. A work plan will be submitted for approval. | | |

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

| | | |
|--|---|------------------|
| Signature:  | OIL CONSERVATION DIVISION | |
| Printed Name: Kelton Beaird | Approved by District Supervisor Signed By  | |
| Title: HES Specialist | Approval Date: 4/4/11 | Expiration Date: |
| E-mail Address: kelton_beaird@oxy.com | Conditions of Approval: | |
| Date: 7-20-09 | Attached <input type="checkbox"/> | |

* Attach Additional Sheets If Necessary

REMEDATION per OCD Rules and
Guidelines. SUBMIT REMEDIATION
PROPOSAL BY:

5/4/11

2 RP-688