<u>District I</u> 1625 N. French I District II			State of New Mexico Energy Minerals and Natural Resources				Form C-141 Revised October 10, 2003					
1301 W. Grand Avenue, Artesia, NM 88210 <u>District III</u> 1000 Rio Brazos Road, Aztec, NM 87410 <u>District IV</u> 1220 S. St. Francis Dr., Santa Fe, NM 87505			Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505				Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form					
		-		ease Notific	atio	n and Co	orrective A	ction	l			
rkmu	1 1/09	162939	R			<b>OPERA</b>	ГOR		🛛 Initia	al Report		Final Repo
Name of Company BOPCO, L.P. 260737						Contact Tony Savoie						
Address 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220 Facility Name Poker Lake Unit #158						Telephone No. 432-556-8730						
Facility Nan	ne Poker I	Lake Unit #1	58			Facility Typ	e E&P API 30	-015-31	690			
Surface Owner Federal				Mineral C	wner	ederal			Lease No.			
		<u></u>		LOCA	TIO	N OF REI	EFASIC					ana dana
Unit Letter	Section	Township	Range	Feet from the		h/South Line	Feet from the	East/V	Vest Line	County		
A	7	24S	30E							Eddy		
			I	atitude_N 32.2	37400	) Longitu	de W 103.9141	150				
				Autor I								
Turne of Dalay	Des Des dus	ad mater		NA I	UKE	COF REL			Valuma	Dagawanada /	200 DL	
Type of Release: Produced water Source of Release: Water transfer pump seal and piping failure.						Volume of Release: 230 bbls.     Volume Recovered: 200 Bbls       Date and Hour of Occurrence     Date and Hour of Discovery						
		i danici pan	3/21/11 time unkown 3/21/11 7:40 a.m.									
Was Immedia	te Notice (		If YES, To Whom?									
		$\boxtimes$										
By Whom? Tony Savoie						Date and Hour 3/21/11 8:20 a.m.						
Was a Watercourse Reached?						If YES, Volume Impacting the Watercourse. RECEIVED						
		·							-H	FUE	VC	
If a Watercou	rse was Im	ipacted, Descri	ibe Fully.	•						APR 05		
									NN	NOCD A	ARTE	SIA
				n Taken.* A wate							on the d	lischarge
piping of the	pump. The	power was sh	ut off and	valves were close ken.*The entire ar	ed isola	ating the pump	. The pump was r	eplaced	later the sa	me day.	tely 15	00 ca ft. The
free standing	water was	removed and t	the saturat	ed area around the	e tanks	inside the con	tainment was exc	avated a	ind stockpi	led on-site,	remedia	ation
activities were	e under wa	y under an app	proved rer	nediation plan. Th								
the produced	water being	g sprayed into	the air.	spill will follow	46 a NIN		an for laster and					
I hereby certit	fy that the i	information gi	ven above	e is true and comp	lete to	the best of my	knowledge and i	spins. inderstar	nd that purs	suant to NM	OCD r	ules and
regulations al	l operators	are required to	o report a	nd/or file certain r	elease	notifications a	nd perform correct	ctive acti	ions for rel	eases which	may e	ndanger
public health	or the envi	ronment. The	acceptan	ce of a C-141 repo	ort by th	he NMOCD m	arked as "Final R	leport" d	loes not rel	ieve the ope	rator of	f liability
				v investigate and r stance of a C-141								
federal, state,					<b>r</b>			·P			•	
			3				<u>OIL CON</u>	SERV	ATION	DIVISIO	<u> </u>	
Signature: / Ong Darens						Annual hu	Approved by District Supervisor					
		1				Approved by	Signed By	Mik	1 Bra	win_		
Printed Name	: Tony Sav	die				· · · · · · · · · · · · · · · · · · ·		· · · · · · · · · · · · · · · · · · ·				
Title: Waste N	Agmt.& Re	emediation Spo	ecialist			Approval Dat	te: 4/6/11	,	Expiration	Date:		
E-mail Addre	ss: TASavo	oie@BassPet.c	com			Conditions of				Attachad		
							diation per OC			Attached	ı ل	
Date: 4/4/11 Phone:432-556-8730   Attach Additional Sheets If Necessary						Guidelines. SUBMIT REMEDIAT PROPOSAL NOT LATER THAN:			ΓΙΟΝ	21	RP.	717
							//					