


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003
Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	COG OPERATING LLC 229137	Contact	Pat Ellis
Address	550 W. Texas, Suite 100, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	Antelope State Tank Battery	Facility Type	Tank Battery
Surface Owner	State	Mineral Owner	
		Lease No. (API#)	30-015-32040



LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
K	36	17S	31E					Eddy

Latitude 32.78841 Longitude 103.82626

NATURE OF RELEASE

Type of Release	Produced fluid	Volume of Release	23bbls	Volume Recovered	21bbls
Source of Release	Water tank	Date and Hour of Occurrence	04/16/2011	Date and Hour of Discovery	04/16/2011 8:00 a.m.
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?		Date and Hour			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			
If a Watercourse was Impacted, Describe Fully.*					
Describe Cause of Problem and Remedial Action Taken.*					
The water transfer pump malfunctioned; it has since been repaired and put back into service.					
Describe Area Affected and Cleanup Action Taken.*					
Initially 23bbls of produced fluid was released and we were able to recover 21bbls with a vacuum truck. All fluid was completely contained inside the facility walls. The spill area measured 5' x 50' inside the bermed area by the tanks. The spill area has been scraped and the contaminated material has been disposed of appropriately. Tetra Tech will sample the spill site area to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation work.					
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.					

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Josh Russo	Approved by District Supervisor: 	
Title: HSE Coordinator	Approval Date: 4/26/11	Expiration Date:
E-mail Address: jrusso@conchoresources.com	Conditions of Approval: Attached <input type="checkbox"/>	
Date: 04/21/2011 Phone: 432-212-2399	Remediation per OCD Rules & Guidelines. SUBMIT REMEDIATION PROPOSAL NOT LATER THAN: 5/26/11	

* Attach Additional Sheets If Necessary

2 RP-761

Bratcher, Mike, EMNRD

From: Joshua Russo [jrusso@conchoresources.com]
Sent: Thursday, April 21, 2011 9:08 AM
To: Bratcher, Mike, EMNRD
Cc: Pat Ellis; Tavaréz, Ike; Dorey, Kim; tom.k.franklin@tetrattech.com
Subject: C-141 - Antelope State Tank Battery
Attachments: img-421105907-0001.pdf

Mr. Bratcher,

Please see attached the C-141 Initial Report for a release that occurred at the Antelope State Tank Battery on 04/16/2011.

Thank you,

Joshua Russo

HSE Coordinator
550 W. Texas Ave, Suite 100
Midland, Texas 79701
Phone: (432) 683-7443
Cell: (432) 212-2399
jrusso@conchoresources.com



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.