

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

Release Notification and Corrective Action

*AKMW 1111656409*

Name of Company OXY USA		Contact Kelton Beaird
Address 1502 W. Commerce Carlsbad, NM 88220		Telephone No. (O) 575-628-4100
Facility Name Jones Canyon 4-5		Facility Type Gas Well

Surface Owner Federal Mineral Owner Lease No. *APR 3001530933*

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
G	4	22S	24E					Eddy

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 50bbls	Volume Recovered 2
Source of Release Check Valve	Date and Hour of Occurrence <i>4-6-11 @ 10:30am</i>	Date and Hour of Discovery
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher - NMOCD, Terry Gregston - BLM	
By Whom? Kelton Beaird - Oxy	Date and Hour See above	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

RECEIVED

APR 21 2011

Describe Cause of Problem and Remedial Action Taken.\*  
Check valve busted. Well was shut-in; vacuum truck was called

NMOCD ARTESIA

Describe Area Affected and Cleanup Action Taken.\*

Fluid ran from the vessel south through the location and into the pasture approx. 1000ft. Area on the location will be delineated as practicable due to hard rock. Area in pasture is solid rock, therefore delineation will not be possible. A water sample will be pulled, sampled, and submitted with the work plan.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>[Signature]</i>		OIL CONSERVATION DIVISION	
Printed Name: Kelton Beaird		Approved by District Supervisor <i>[Signature]</i>	
Title: HES Specialist		Approval Date: <i>4/26/11</i>	Expiration Date:
E-mail Address: kelton_beaird@oxy.com		Conditions of Approval: Remediation per OCD Rules & Guidelines. <b>SUBMIT REMEDIATION PROPOSAL NOT LATER THAN:</b>	
Date: 4-8-11		Attached <input type="checkbox"/> <i>2RP-762</i>	

\* Attach Additional Sheets If Necessary

*5/26/11*