

701 Cedar Lake Blvd.	•	Oklahoma City, OK 73114-7806
(405) 478-8 77 0	•	Fax: (405) 478-1947

23 March 2001

New Mexico Energy, Minerals and Natural Resources Department Attn: William C. Olson, Hydrologist Oil Conservation Division 1220 South St. Francis Drive Santa Fe, New Mexico 87505



Re: South Langlie Jal Unit Stage I Abatement Plan

Dear Mr. Olson:

Attached is Chaparral Energy Inc.'s initial Abatement Plan covering the possible pollution of groundwater by past oil and gas production operations. Steps are already being taken to remediate the unit surface and gather data pertaining to possible soil and groundwater contamination. Should you require anything further please contact me at the numbers below.

Sincerely,

Robert C. Lang IV, REM, CEA Environmental, Health & Safety Manager (405) 478-4643 Ext. 130 (O) (405) 478-2034 (F)

cc: Chris Williams, OCD Hobbs District Office Clay Osborn

OCD Exhibit No. Case No. 13061 July 15, 2003 may 12,