



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

GARY E. JOHNSON
Governor
Jennifer A. Salisbury
Cabinet Secretary

Lori Wrotenbery
Director
Oil Conservation Division

March 22, 2001

Shanley Oil Company
PO Box 802415
Dallas, Tx 75380

RE: Harris "14" # 1
UL B, Section 14, T6S, R33E
API # 30-041-20342

A review of our records and recent inspections show that the above referenced well has been shut in for an extended period of time. Order R-9210 states that an operator can not leave a well shut in longer than a year. The following options are available for the future of the above well.

1. Restore the well to service.
2. Set plug, conduct mechanical integrity test, and request temporary abandoned status.
3. Submit a proposal to plug and abandon the wells, proceed with plugging on a timely basis after the proposal has been evaluated, amended and or approved.

To avoid further action, we request that you exercise one of the above options no later May 22, 2001. We request that you notify this office 24 hours prior to any operation in order to witness the operation, either repair or plugging and pressure test upon completion of repairs or to request TA status.

Very truly yours
OIL CONSERVATION DIVISION

A handwritten signature in black ink, appearing to read "BEP", written over the typed name and title.

Billy E. Prichard
Deputy Inspector, District 1
505 393-6161 Ext 107
505 369-6412 Cellular
bprichard@state.nm.us

Cc:
Chris Williams
Gary Wink
Sylvia Dickey
file