Bell Lake Area, Lea County, NM Total 2nd Bone Spring Porosity-Feet (Phi-H)



- Contour Interval: 10'
- Phi-H ~28' throughout section 18

BELL LAKE 7909 JV-P PALON A BLANCO '17' 13 18 7909 JV-P BELL LAKE PALOMA BLANCO 17 FE 240

BEFORE THE OIL
CONSERVATION DIVISION
Santa Fe, New Mexico
Exhibit No. 20
Submitted by: CHEVRON USA INC.
Hearing Date: February 20, 2014