


JAMES RANCH UNIT 121H AREA


EVIDENCE OF WATER ENCROACHMENT

Structure Map - Top Delaware Lower Brushy Canyon

James Ranch Unit, Eddy Co., New Mexico



N49°E
Delaware Fracture Orientation
from FMI Analysis



OCD CASE NOS.
15219 AND 15231

BOPCO
Exhibit # 7