


Structural Cross Section A – A'

Lateral
Interval



BEFORE THE OIL CONSERVATION DIVISION
Santa Fe, New Mexico
Exhibit No. 12 – Case Nos. 15609
Submitted by: COG Operating LLC
Hearing Date: January 5, 2017