

28-Nov-07

Well Inspection History

API Number: 30-015-34892-00-00

Well Name & No.: ROBERTS 13

Operator: CHAPARRAL ENERGY LLC,

District: ARTESIA

County Name: EDDY

Field: ROBERTS 13

Legal: S: 13 T: 17S R: 26E

Well Type: GAS (PRODUCING)

Insp. Dt.	Insp. Type	Insp. Purpose	Insp. No.	RmdyRqDt	Insp. By	Viol. SNC	Failed Codes
7/12/2007	File and Compliance Review	Normal Routine Activity	iPCH0719333		210		
Road to wet to get into location, it looks like pumping unit has been removed from location							
7/12/2007	File and Compliance Review	Normal Routine Activity	iGEG0719333		209	Y	
A review of the well file for this well shows no completion report or Request for Allowable as required by OCD Rule 19.15.13.1105 and 1104.							
4/3/2007	Routine/Periodic	Normal Routine Activity	iPCH0709336		210		
Well is drilled and Active.Location OK							

Total Inspections Performed: 3

Chaparral Energy, LLC
Case 14006
OCD Exhibit No. 4