

27-Dec-07

Well Inspection History

API Number: **30-015-30964-00-00**Well Name & No.: **RAMAPO**Operator: **ROJO GRANDE COMPANY LLC, FLOYD JO**District: **ARTESIA**County Name: **EDDY**Field: **RAMAPO**Legal: **S: 36 T: 17S R: 27E**Well Type: **OIL (PRODUCING)**

Insp. Dt.	Insp. Type	Insp. Purpose	Insp. No.	RmdyRqDt	Insp. By	Viol. SNC	Failed Codes
10/18/2007	Routine/Periodic	Normal Routine Activity	iREH0729148		214		
Well still shows no production since 11/1/2001. PJ is in tact. PJ motor has old/cracked belt. Electrical line is connected to PJ motor and leads to a power pole @ 200 yards west of the location. Power switch at pole is in off position. Meter is not installed in meter box on pole. A note left by CVE dated 10/10/07 states operator needs to contact CVE front office for a connect. Flowline is intact and valve is open. Photos taken.							
5/11/2007	Inactive Well Verification	Normal Routine Activity	iREI07131463		213	Y	
Violation of rule 19.15.4.201. Flow line closed. Last production reported 11/01/2001. Violation rule 116. Contamination around wellhead. Please submit paperwork to properly P&A this well, or bring well back into compliance. Please submit C-144 Pit closure form by compliance due date with pit closure to occur within 1 month of compliance due date.							
3/8/2006	Compliance Verification	Enforcement Action Follow-u	iVAB06067276		208	Y	
2/27/2006	Compliance Verification	Normal Routine Activity	iGEG0605846		209	Y	
Shut-in. Electricity off. No production reported since 2001.							
11/5/2004	Routine/Periodic	Normal Routine Activity	iGEG0431042		209		
Location needs attention. Equipment OK.							
9/8/2003	Routine/Periodic	Normal Routine Activity	iGEG0325137		209		
A-OK. All Equipment and Location in Good Shape.							

Total Inspections Performed: 6

Rojo Grande Company LLC

***Case 13980
OCD Exhibit No. 4***