

29-Jan-08

Well Inspection History

API Number: 30-015-05739-00-00

Well Name & No.: DONNELLY PAN AMERICAN

Operator: TOM R CONE, DWAYNE BURRIS

District: ARTESIA

County Name: EDDY

Field: DONNELLY PAN AMERICAN

Legal: S: 5 T: 19S R: 31E

Well Type: OIL (PRODUCING)

Insp. Dt.	Insp. Type	Insp. Purpose	Insp. No.	RmdyRqDt	Insp. By	Viol. SNC	Failed Codes
4/23/2007	Routine/Periodic	Normal Routine Activity	iREH0711347		214		
OK. All Equipment and Location in Good Shape.							
10/26/2005	Routine/Periodic	Normal Routine Activity	iCLB05299499		212		
OK. All Equipment and Location in Good Shape. PJ operating.							
1/8/2004	Routine/Periodic	Normal Routine Activity	iMCS0400840		205		
Tank Battery is located to the north east of well near the road. 2 210 bbl tanks, 1 separator, 300' of flowline to well, separator, 1 production pit that will require closure as per guidelines. Junk on loc., one tank is full of fluid. Duncan Withlocke tank at 8' 11" of misc. fluid. a gauged by Dunc, Historic hydrocarbon visible under and near stock tanks appears minor in volume, As per Paul Evans Historic hydrocarbon can be placed in producing pit when closed. Separator has fluid. Well has pumping unit, 2 power poles, 4 deadmen, historic hydrocarbon around BH and pumping unit est. 20'x20' with unknown verticle. Old drilling pit located to north of well will need ripping and reseeding as per Paul Evans. Lease road will require berming as per Paul Evans. The Historic hydrocarbon can be placed in workover pit as per Paul Evans.							
8/29/2002	Routine/Periodic	Status Check	iPCH0224143		210		
FOLLOW UP INSPECTION. NO WORK DONE. ELECTRIC METER PULLED, NO WELL SIGN							
6/10/2002	Routine/Periodic	Normal Routine Activity	iMLB02161443		211		
No electricity to pump jack. Meter has been pulled at pole. Well is idle. No work has been done at well site. No well sign.							

Total Inspections Performed: 5

Tom R. Cone

**Case 14076
OCD Exhibit No. 7**