

14-Mar-08

Well Inspection History

API Number: **30-015-20094-00-00** Well Name & No.: **RESLER YATES STATE**
Operator: **SANDLOTT ENERGY (JACKIE BREWER D)** District: **ARTESIA** County Name: **EDDY**
Field: **RESLER YATES STATE** Legal: **S: 32 T: 18S R: 28E**
Well Type: **OIL (PRODUCING)**

Insp. Dt.	Insp. Type	Insp. Purpose	Insp. No.	RmdyRqDt	Insp. By	Viol. SNC	Failed Codes
7/24/2007	Routine/Periodic	Normal Routine Activity	iMLB07205440		211		
Contamination and oil standing around pumping unit. Electric meter has been pulled at the well site but an electric line has been laid to a power meter near the Resler Yates 381 well. No indication of recent activity at this well site other than the standing oil.							
7/5/2006	File and Compliance Review	Normal Routine Activity	iPCH0618641		210		
No belts on pumping unit motor, no electrical hook up. Contamination around wellhead							
8/30/2005	Routine/Periodic	Normal Routine Activity	iMLB05242536		211		
No Motor on Pumping Unit. No indication of recent activity at well site.							
8/20/2004	Routine/Periodic	Normal Routine Activity	iGEG0423339		209		
No Motor on Pumping Unit.							
10/19/1999	Routine/Periodic	Status Check	iELG0003125		207		
A-OK. All Equipment and Location in Good Shape.							

Total Inspections Performed: 5

Jackie Brewer D/B/A
Sandlott Energy
Case 14074
OCD Exhibit No. 10